Form 3160-5 UNITED STA (November 1983) (Formerly 9-331) DEPARTMENT OF THE BUREAU OF LAND MANA	INTERIOR	SUBMIT IN TRIPLICAT (Other instructions reverse side)	
SUNDRY NOTICES AND RE (Do not use this form for proposals to drill or to deep Use "APPLICATION FOR PERMIT-" for	en or plug back to		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL X GAS WELL X OTHER			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR TEXACO EXPLORATION AND PRODUCTION INC.			8. FARM OR LEASE NAME LYDIA RENTZ
3. ADDRESS OF OPERATOR			9. WELL NO.
P. O. Box 3109, Midland, Texas 79702			11
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 			10. FIELD AND POOL, OR WILDCAT
At surface 840' FSL & 1820' FEL, UNIT LETTER O, SW/SE			11. SEC., T., R., OR BLK. AND SURVEY OR AREA
			SEC.19, T-25-N, R-3-W
	(Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
AP# 30 039 25303 GR-7254', K		· · · · · · · · · · · · · · · · · · ·	RIO ARRIBA NM
16. Check Appropriate Box	To Indicate !	Nature of Notice, Rep	ort, or Other Data
NOTICE OF INTENTION TO: SUBSEQUE			EQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE		FRACTURE TREATMENT	X ALTERING CASING
SHOOT OR ACIDIZE ABANDON*		SHOOTING OR ACIDIZING	X ABANDONMENT*
REPAIR WELL CHANGE PLANS		(Other) COMPLETION	x
Completion or Recomple			ts of multiple completion on well impletion Report and Log form.)
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta posed work. If well is directionally drilled, give subsurf work.)⁶ 	te all pertinent deta ace locations and	ails, and give pertinent dates, is measured and true vertical depr	ncluding estimated date of starting any pro- ths for all markers and zones pertinent to this
*FIELDS: BLANCO, MESA VERDE AND WEST LIM 1. MIRU SERVICE UNIT. CLEAN OUT CASING TO 93. SCHLUMBERGER RAN GR-CET-CCL. 2. PERFED LOWER DAKOTA w/ 2 JSPF: 8045-FRAC w/ 62000 GAL XLG AND 164000# 20/46 3. SET RBP @ 8030'. PERF UPPER DAKOTA w/ 1/2% NEFE. FRAC w/ 55000 GAL XLG AND 17 4. SET RBP @ 7800'. PERF GALLUP w/ 2 JSP FRAC w/ 134232 GAL XLG AND 307010# 20/4 5. TIH AND RETRIEVED RBPS. CLEAN OUT SAND 6. TIH WITH 2 7/8 TUBING, PUMP AND RODS. S 7. PUMPED 192 BO, 48 BLW, AND 128 MCFPD 8. TESTING	PBTD OF 8190 -8076. 62 HOI 0 SAND. 10-26 / 2 JSPF: 789 1000# 20/40 F: 6964-7164 40 SAND. 11-6	D'. TESTED CASING TO S LES. DOWELL ACIDIZED 6-93. 11-7914. 46 HOLES. DO SAND. 10-27-93. 1. 200 HOLES. DOWELL 01-93. E @ 8064'.	w/ 1000 GAL 7 1/2% NEFE.

18. I hereby certify that the foregoing is true and correct

SIGNED C.P. Resham / CWH TITLE DRILLING OPERATIONS MANAGER

(This space for Federal or State office use)

SHIRLEY MONDY

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE DRILLING OPERATIONS MANAGER

RIO PUERCO RESOURCE AREA

DATE JAN 5 1994