	UNITED STATES TMENT OF THE INTERIOR (Other instruction of the interior of the interior of the instruction of the interior of t	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NM-015014 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for pro Use "APPL	oposals to drill or to deepen or plug back to a different resellCATION FOR PERMIT—" for such proposals.)	rvolr.
I. OIL WE'LL GAS WELL OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
Amerada Hess Corporation 3. ADDRESS OF OPERATOR Drawer D, Monument, New Mexico 88265 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		McKenzie-Federal
		10. FIELD AND POOL, OR WILDCAT
990' FSL & 890' F	WL	Otero Gallup/Basin Dakota 11. sec., T., B., M., OR BLE. AND SURVEY OR AREA 25 - 25N - 6W
14. PERMIT NO.	15. ELEVATIONS (Show whether LF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	6676'	Rio Arriba New Mexico
16. Check	Appropriate Box To Indicate Nature of Notice, R	eport, or Other Data
NOTICE OF INT	TENTION TO:	SUBSEQUENT REPORT OF:
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL X	MULTIPLE COMPLETE ABANDON* CHANGE PLANS WATER SHUT-OF FRACTURE TREA SHOOTING OR AG (Other) (NOTE: R	TMENT ALTERING CASING CIDIZING ABANDONMENT*
Plan to pull produplug, locate hole	operations (Clearly state all pertine it details, and give per ctionally drilled, give subsurface locations and measured and uction tbg., re-run retrievable brins 5-1/2" csg. and squeeze same wi	dge plug & pkr., test bridge th 400 sks. Class G cement
17. DESCRIBE PROPOSED OR COMPLETED Corproposed work. If well is directly nent to this work.)* Plan to pull produplug, locate hole mixed 2% CaCl. Wo	DEFERATIONS (Clearly state all pertine it details, and give pertine and details, and give pertine and measured and details, and measured and details, and measured and details, and measured and details, re-run retrievable bri-	tinent dates, including estimated date of starting any true vertical depths for all markers and zones pertidge plug & pkr., test bridge th 400 sks. Class G cement
17. DESCRIBE PROPOSED OR COMPLETED Corproposed work. If well is directly near to this work.)* Plan to pull produplug, locate hole mixed 2% CaCl. Wo	DEFERTIONS (Clearly state all pertine it details, and give pertine and details, and give subsurface locations and measured and uction tbg., re-run retrievable brins 5-1/2" csg. and squeeze same with 200 & drill out cement and test. If the tion tbg. & resume production.	tinent dates, including estimated date of starting any true vertical depths for all markers and zones pertidge plug & pkr., test bridge th 400 sks. Class G cement

*See Instructions on Reverse Side