

copy to  
file  
to  
Cmery

CUBA RANGER DISTRICT, CUBA, NEW MEXICO

2710

November 3, 1965

Bolack - Greer Inc.  
158 Petroleum Center Building  
Farmington, New Mexico

Dear Sirs:

Since completing your well, 9-Canada-Ojitos, in the NE $\frac{1}{4}$  NW $\frac{1}{4}$ , section 2, T-25-N, R-1-W, N.M.P.M. more than a month ago you have been requested several times to drain the drilling mud pit. This pit, being in a stream bed, is in a very poor location and could easily be washed out by any storm in the area.

The terms of both your Bureau of Land Management Lease and Forest Service Permit state that the pits will be covered or fenced shortly after completion of drilling. Since drilling was completed more than a month ago and the pit is in the stream bed, we must ask you to drain and cover it immediately.

Although you abandoned your G-34 Puerto Chiquito well more than a year ago the site still contains much casing and other drilling apparatus. This material also needs to be cleaned up immediately.

We sincerely appreciate your cooperation in the past and do hope these two matters may be remedied within the very near future.

Yours truly,

  
Jay W. Eby  
District Forest Ranger

JME:ta

cc: U.S. Geologic Survey  
N.M. State Oil Conservation Commission