Form 9-311 (May 1963)

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

Form approved.
Rudget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.


SF 078912

G	DI OTOTE			
SUNDRY NOTI (Do not use this form for propose Use "APPLICA"	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME		
			7. UNIT AGREEMENT NAME	
OIL GAS X OTHER	Lindrith			
NAME OF OPERATOR			8. FARM OR LEASE NAME	
El Paso Natural Gas Cor	Lindrith			
3. ADDRESS OF OPERATOR	9. WELL NO.			
P. O. Box 990, Farming	40			
LOCATION OF WELL (Report location cl	10. FIELD AND POOL, OR WILDCAT			
See also space 17 below.) At surface			So. Blanco PC	
110/s, 840/w	11. SEC., T., R., M., OR BLK. AND SUBVEY OR ABEA Sec. 10, T24N, R3W			
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
	69 1 5 DF		Rio Arriba	NM
16. Check Ap	propriate Box To Indicate N	ature of Notice, Report, or C	Other Data	
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	
FRACTURE TREAT	CLTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	
SHOOT OR ACIDIZE	ABANDON*	shooting or acidizing Lother) Tubing Ins	ABANDONMEN	T*
REPAIR WELL	CHANGE PLANS		s of multiple completion (n Well
(Other)		Completion or Recomp	detion Report and Log for	m.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.).

Ran 96 jts, 1 1/4" 2.40# 10R NU IJ V-55 Vinson tubing. Total of 3113' set at 3123'.





18. I hereby certify that the foregoing is true and correct SIGNED A Foliart	TITLE .	Production Engineer	DATE1/4/73
(This space for Federal or State office use)			
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE .	•	DATE

