(SUBMIT IN TRIPLICATE)

UNITED STATES

Santa Fe....

Lease No.

078861

GP0 061040

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Unit

SUNDRY NOTICES AND DEPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL. X	SUBSEQUENT REPORT OF WATER SHUT-OFF. SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY
(INDICATE ABOVE BY CHECK MARK NATUI	RE OF REPORT NOTICE, OR OTHER DATA)
Kinebeto-Federal Well No. 1 is located one ft from [N	Mar 17 , 1960.
	line and 990 . It. from $\binom{E}{W}$ line of sec. 21.
SW NE NE 21 (% Sec. and Sec. No.) (Twp.) (Kange,	NMPM (Meridian)
Bisti-Gallup San Juan (County or Sabdi	vision) New Mexico (State or Territory)
The elevation of the derrick floor above sea level is	* *
DETAILS O	
(State names of and expected depths to objective sands; show sizes, weig ing points, and all other im	to the state of th
PBTD 5359*. 8-5/8" - 302*, 5\darksin - 5404*, 19	25 sx. Perforations 5320-25, 5329-33.
Production has declined and, as shown by the limit. It is, therefore, proposed to plud a Squeeze w/cement perforations 5320-25 and the limit and shoot off pions above cemes. Place 100° cement plud at point where of as casing is pulled place cement plud to Place 100° plug from 252 to 352°. Plug top of surface pipe w/cement and it Restore surface.	well and salvage 52" as follows: and 5329-33. ent. casing is narted. chrough Pictured Cliff Zone 1640-1815. nstall marker.
ast Production: March 1959	by the Geological Survey before
Company Gulf Cil Corporation	on the commenced.
Address Production Department	Carrier Co. Sec. 18
PO. Box 1346	By A TOE
Salt Lake City, Utah	Title Area Production Manager