Form 9-331 (May 1963)

16.

UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

SUBMIT IN TRIPLICATE.

Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SF 0790K1

| GEOLOGICA | L 2011 | V L | |
|-----------|--------|-----|------|
| | | | |

| | (Do not use this form for proposa | ds to drill or to deepen or plug back to a different reservoir. | | |
|------|---|--|--------------------------------|--|
| ι. | | | 7. UNIT AGREEMENT NAME | |
| | WELL GAS OTHER | | East Pisti Unit | |
| 2. 1 | NAME OF OPERATOR | | 8. FARM OR LEASE NAME | |
| | Skelly Oil Company | | | |
| | ADDRESS OF OPERATOR | | 9. WELL NO. | |
| | 1860 Lincoln Street, I | Cenver, Colorado 80203 | 110 | |
| | LOCATION OF WELL (Report location cl | 10. FIELD AND POOL, OR WILDCAT | | |
| | See also space 17 below.) At surface | Bicti Lower Cellus 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA. | | |
| | 1980' FML and 1930' FM | | | |
| | | | Sec. 8-20N-00 | |
| 14. | PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) | 12. COUNTY OR PARISH 13. STATE | |
| | | 67391 CR | San Juan Mes liexic | |

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOT | ICE OF IN | TENTION TO: | SUBSEQUENT REF | ORT OF: |
|---------------------|-----------|----------------------|-----------------------|---|
| TEST WATER SHUT-OFF | | PULL OR ALTER CASING | WATER SHUT-OFF | REPAIRING WELL |
| SHOOT OR ACIDIZE | | ABANDON* | SHOOTING OR ACIDIZING | ABANDONMENT* |
| REPAIR WELL (Other) | | CHANGE PLANS | (Other) | iple completion on Well port and Log form.) |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

All depths shown are from ground level. 6-16-71 - III & DU Astec Well Dervice Unit.

Ran 2" tubing. Spotted cement plug from 5419' to 5319'. Pulled tubing Worked 4-1/2" coping free and shot off casing at 1805'. Pulled 56 joints 1800' of 4-1/2" casing. Spotted copent plug from 1855' to 1855'. Spotted comput plug from 984' to 984'. Spotted 10' coment plug in surface casing. Installed dry hole marker. Completed P & A 6-18-71.



| 18. I hereby certify that the foregoing is true and correct SIGNED | TITLE: | Inad Gleti | DATE 10-15-55 |
|--|--------|------------|---------------|
| (This space for Federal or State office use) | | | |
| APPROVED BY | TITLE: | 4 | DATE |