

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-4912-3

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	East Bisti Unit
3. Address of Operator	8. Farm or Lease Name
1850 Lincoln Street, Denver, Colorado 80203	
4. Location of Well	9. Well No.
UNIT LETTER <u>N</u> , <u>760</u> FEET FROM THE <u>South</u> LINE AND <u>1830</u> FEET FROM	10. Field and Pool, or Wildcat
THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>24N</u> RANGE <u>10W</u> NMPM.	Bisti Lower Gellup
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
6854' GR	San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

All depths shown are from ground level.

6-25-71 - ME & RU Aztec Well Service Unit.

Spotted cement from 5437' to 5337'. Pulled tubing. Worked 4-1/2" casing free at 800'. Perforated from 1815' - 1817'. Spotted cement from 1817' to 1667'.

Perforated from 1066' - 1067' w/4 shots. Spotted cement at 1067' to 970'.

Shot off 4-1/2" casing at 831'. Pulled 28 joints 4-1/2" casing 831'.

Spotted cement at 872' to 772', 50' inside & 50' outside the 4-1/2" casing stub.

Spotted 10' cement plug in surface casing. Installed dry hole marker.

Completed P & A 6-26-71.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. L. Biles</u>	TITLE <u>Lead Clerk</u>	DATE <u>10-15-71</u>
APPROVED BY <u>Emory C. Ames</u>	TITLE <u>Sup. Pnt. III</u>	DATE <u>12-6-71</u>
CONDITIONS OF APPROVAL, IF ANY:		