

5 BLM 1 File 1 James Fullerton
1 Meridian, Fmn (Attn: Lora Larson)

Form 3160-5
(June '990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
BLM MAIL ROOM

96 MAY 17 AM 2:46

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other P&A

2. Name of Operator
Dugan Production Corp.

3. Address and Telephone No.
P.O. Box 420, Farmington, NM 87499 (505) 325-1821

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1520' FSL & 790' FWL
Sec. 5, T24N, R9W

5. Lease Designation and Serial No.

N14 16759

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Big Bird No. 1

9. API Well No.

30 045 25451

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

San Juan County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☐ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5/15/96 - this well was plugged and abandoned as follows:

- 1.) Set cement retainer @ 3450'. Could not pump below it at 2000 psi. Spotted 12 sacks class "B" cement on top of retainer.
- 2.) Pulled up hole to 2684'. Spotted 15 sack class "B" plug top of plug @ 2515'.
- 3.) Pulled up hole to 1798'. Spotted 28 sack class "B" plug. Top of plug @ 1432'.
- 4.) Pulled up hole to 1082'. Spotted 25 sack class "B" plug. Top of plug @ 750'.
- 5.) Pulled up hole to 269'. Filled to surface with 25 sacks class "B". Tied onto bradenhead and squeezed with 56 sacks class "B".
- 6.) Cut off wellhead and set dry hole marker.

Job was witnessed by Joe Sanchez (BLM).

14. I hereby certify that the foregoing is true and correct

Signed

Gary Brink

Title

Operations Manager

Date

5/16/96

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

APPROVED

MAY 21 1996

DISTRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC