Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. User Form 3160-3 (ARD) for such proposals.		6. If Indian, Allottee or T	6. If Indian, Allottee or Tribe Name	
0000	Other instructions on reverse side	5 Fil 1: 24 Jicarilla Apache 7. If Unit or CA/Agreeme		
Oil X Gas Well Other 2. Name of Operator Marathon Oil Company	OCT 2000	8. Well Name and No. Jicarilla Apache 9. API Well No.	No. 3	
3a. Address P.O. Box 2490 Hobbs, NM 88440 4. Location of Well (Footage, Sec., T., R., M., or Survey Description of Well (Footage,	M. CON. DV 505 / 393-710 ption)	30-039-06260	red Cliffs	
12. CHECK APPROPRI	ATE BOX(ES) TO INDICATE NATURE	OF NOTICE, REPORT, OR OTHER DATA	NM	
TYPE OF SUBMISSION		TYPE OF ACTION		
Notice of Intent X Subsequent Report	Acidize Deepen Alter Casing Fracture Tre Casing Repair New Constru	at Reclamation Well	ter Shut-Off Integrity er	
Final Abandonment Notice	Change Plans Plug and Ab Convert to Injection Plug Back	andon Temporarily Abandon RC PC Water Disposal	and DHC	
13. Describe Proposed or Coommpleted Operation (clear If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. If testing has been completed. Final Abandonment No determined that the final site is ready for final inspection	tele norizontally, give substittace locations and formed or provide the Bond No. on file with the operation results in a multiple completion offices shall be filed only after all requirement	BLM/BIA. Required subsequent reports shall be fi	markers and zones iled within 30 day	
7/25 RU pulling unit. ND wellhea Test RBP, OK. Rel pkr, POOH 7/28 Perf PC 2918-44, 3018-24, 3 15% acid. Sand frac w/8880 8/1 Rel pkr at 2800°, POOH. RIH 8/3 RIH w/2 3/8" tbg. Tag fill	nd. NU BOP. POOH w/tbg. RIH w. I. Run GR/CCL log from 3694-2 1028-34 w/2 SPF, 76 holes. RII gals 70Q N2 foam containing (I, tag sand at 3450'. Clean of on plug at 3815'. Clean sand	/RBP & pkr. Set RBP at 3700', pkr 700'. I w/pkr, set at 2800'. Acidize w/: 50,000# sand. Open well, flow back it to RBP at 3694'. Rel RBP, POOH off RBP, push down to 3885', POOH I w/2 3/8" tbg. Tag btm at 3885'.	1000 gals k.	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Kelly Cook	Date 9/2	ecords Processor 2/00		
Approved by	SPACE FOR FEDERAL OR STATI			
Conditions of approval, if any, are attached. Approval of	this notice does not warrant or occ	Pertro. Eg. OCT 05	2000	
certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations thereon.	those rights in the subject lease	•		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.