Form 3160-5 (December 1989)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS		Jicarilla Tribal 102
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such இரிக்கி இடித்தில் இத		6. If Indian, Allottee or Tribe Name
USE APPLICATION FOR	K LEKWII - 101 and Machinal 2 Will 10. 02	Jicarilla Apache
SUBMIT IN TRIPLICATE CLE ALBUQUERQUE, N.M.		7. If Unit or CA, Agreement Designation
1. Type of Well		8. Well Name and No.
OIL SAS WELL OTH	IER	
2. Name of Operator		Jicarilla Apache 102 #1
Amoco Production Company Melissa Velasco-Price		9. API Well No.
3. Address and Telephone No.		30-039-06549
P.O. Box 3092 Houston, TX 772533 (281) 366-2548		10. Field and Pool, or Exploratory Area
		Tapicito Pictured Cliffs
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
		Die Assibe New Mexico
990' FSL & 1650' FWL Sec. 10	T26N R04W Unit N	Rio Arriba New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION		DN .
Notice of Intent	Abandonment	Change of Plans
_	Recompletion	New Construction
Subsequent Report	☐ Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
Other Re-stimulation Workover		
(Note: Report results of multiple completion on Well Completion or		
Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed.		
13. Describe Proposed or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		
MIRU SU. ND tree, NU BOP. Tag for fill. POOH with tbg. RIH with frac string x pkr. Frac with 50,000 lbs sand x nitrogen foam. Flow back. POOH with frac string. RIH with bailer and check for fill. Run 2-3/8" production tbg. RDMO SU.		
Maria		
	2000 S	
14. I hereby certify that the foregoing is true and corr	`	
Signed 9/1000000000000000000000000000000000000	CC Title Permitting Assistant	Date05/16/00
(This space for Federal or State office use)		
Approved by at win Malester Conditions of approval, if any:	Lands and Mineral Resources	Date 5-24-80
S. S		