

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

PERMIT IN TRIPLICATE  
(Other instructions on reverse side)

Dudger Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or in deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

JUN 16 1986

OIL WELL ☒ GAS WELL ☐ OTHER ☐

NAME OF OPERATOR

Amoco Production Co.

ADDRESS OF OPERATOR

BUREAU OF LAND MANAGEMENT

FARMINGTON RESOURCE AREA

501 Airport Drive, Farmington, N M 87401

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.

At surface

835' FNL x 2310' FWL

5. LEASE DESIGNATION AND SERIAL NO

Jicarilla Apache 118

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla Apache A 118

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

Ojito Gallup-Dakota

11. SEC., T., R., M., OR ALE, AND SURVEY OR AREA

NE/NW Sec 36, T26N, R3W

12. COUNTY OR PARISH

13. STATE

Rio Arriba

New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PLUG OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

XX

7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Moved in and rigged up service unit on 6-4-86. Killed well with 75 bbl 2% KCL. Tagged for fill and did not find any. Killed well again with 120 bbl 2% KCL. Changed tubing from 2 3/8" to 2 7/8". Killed well with 24 bbl 2% KCL. Tripped in with pump and rods. Released the rig on 6-10-86.

Moved in and rigged up service unit on 6-11-86. Respaced the pump and returned the well to production. Released the rig on 6-11-86.

RECEIVED

JUL 02 1986

OIL CON. DIV.  
DIST. 3

I hereby certify that the foregoing is true and correct

SIGNED

TITLE Adm. Supervisor

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE JUN 30 1986

CONDITIONS OF APPROVAL IF ANY:

FARMINGTON RESOURCE AREA

BY

\*See Instructions on Reverse Side