UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

YORM AFFROVED

5. Lease Designation and Ser. No

NM 28709

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" For such proposals

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation

1. Type of Well:

Oil Well XX Gas Well

Other

5

S. Well Name and No. Divide # 3

2. Name of Operator

M W Petroleum Corporation

9. API Well No.

30-039-02350

3. Address and Telephone No.

87401 505-325-0318 304 N. Behrend Ave., Farmington, NM

10. Field and Pool, or Exploratory Are Gavilan Mancos

II. County or Parish, State

1. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1780' FSL, 2120' FWL, $_{V}$ Sec. 35 T26N-R2W Rio Arriba NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

	TYPE OF SUBMISSION	TYPE OF	ACTION
	Notice of Intont	Abandonment Recompletion	Change of Plans New Construction Non-Routine Presturing Water Shut-Off Conversion to Injection
XX 4	Subsequent Report	Plugging Back Casing Repeir Altering Casing	
1	Final Abandonment Notice	X Other Status of well (Note: Report results of multiple completions on Wel	Water 1 Completion or Recompletion Report and LogPorm.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to

MW Petroleum opened the Pictured Cliffs formation in this well in March 1994. The formation tested very little gas with a large quantity of water--not economical to produce. THE PC was then squeeze cemented off, returning the well to Gavilan Mancos production. Due to the economics of producing the Gavilan Mancos, the well was temporarily shut-in in February 1996, then returned to production on 1-30-97 and is still producing.

As with the Divide #1, Tapacitos Com #2, Tapacitos Com #4, this well is also being evaluated for a horizontal re-completion in the Gavilan Mancos and/or re-completion in Mesa Verde formation, waiting on results from an offset operator, Mallon Oil Co., on their recompletion testing. The recent increase in gas prices has this well economical to produce.

Production Foreman

Chief, Lands and Mineral Resources

Conditions of approval, if any:

Title 18 U.S.C. Soction 1001, makes it a crime for any person knowingly to make to any department or agency to the United States any false, fictitious or

Fraudulent statements or representations as to any matter within its jurisdiction.

