Form 3160-5	HAUTED CTATEC	GUDAUM IN MOVEL OF THE	Form approved. Budget Bureau No. 1004-0135
(Mariambar 1002)	UNITED STATES DEPARTMENT OF THE IN	SUBMIT IN TRIPLICATE® (Other instructions on reverse side)	Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
(. 0	BUREAU OF LAND MANAGE		MN 04073A
SUND (Do not use this for	ORY NOTICES AND REPORT OF THE PROPERTY OF T	RTS ON WELLS plug back to a different reservoir. such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.	7		7. UNIT AGREEMENT NAME
WELL X GAS WELL 2. NAME OF OPERATOR	OTHER		8. FARM OR LEASE NAME
=-	nd Gas Corporation	Bootstrap Com	
3. ADDRESS OF OPERATOR		87499 RECEIVED	9. WBLL NO.
4. LOCATION OF WELL (Rep.	, Farmington, New Mexico ort location clearly and in accordance wi		10. PIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface DEC 2 3 1986			- Undesignated Gallup/Dik 11. SHC., R., M., OR BLK. AND SURVEY OR AREA
	0' FNL and 750' FEL	BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA	Sec.31, T26N, R2W
14. PERMIT NO.	15. ELEVATIONS (Show whe		Rio Arriba New Mexico
16.			·
Check Appropriate box to indicate Hardle of Honey, Report, of			ENT REPORT OF:
TEST WATER SHUT-OFF		WATER SHUT-OFF	REPAIRING WELL
PRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other) Location o	f line X of multiple completion on Well
Ŋ	The gas line is on the ea	ast side of the access roa	d.
19. I haraby cardes that the	ne foregoing is true and correct	JAN 12 1987	PPKCVE JANO 5 1986 Js/ J. Stan McKee AREA MANAGER
SIGNED SIGNED	TITLE	Operations Manager	DATE 12/22/86
(This space for Federal			
		<i>,</i>	DATE
APPROVED BY	TITLE	·	UAIN

TITLE __