

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Budget Bureau No. 1001-0135
Expires August 31, 1985
LEASE REGISTRATION AND ACQUISITION NO.

NM 03381

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Caulkins Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 340 Bloomfield, New Mexico 87413

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 11 below.)
At surface

1664' F/S and 1611' F/E

5. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Breech "B"

9. WELL NO.

172-R

10. FIELD AND POOL, OR WILDCAT

Basin Dakota - Blanco MV

11. SEC., T., R., W., OR BLK. AND
CORNER OR AREA

Section 7, 26N 6W

16. PERMIT NO.

18. ELEVATIONS (Show whether DT, AT, CA, etc.)

6412 GR

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

19. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

☐
☐
☐
☐
☐

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

☐
☐
☐
☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

☐
☐
☐

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

20. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and target point to this work.)

APD as amended approved April 6, 1989.

It is now requested that this application be canceled.

This well was to be drilled to replace old Dakota well No. 172. Since receiving approval old well did return to producing and casing was repaired successfully, therefore no need for new well.

Right-of-way application had not been filed.

RECEIVED

DEC 01 1989

LOCATION DIV.

21. I hereby certify that the foregoing is true and correct

SIGNED Charles E. O'Quinn TITLE Superintendent

DATE 9-21-89

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

DATE _____

*See Instructions on Reverse Side