

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
BLM

5. Lease

NMNM-03554

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals)

070 FARMINGTON, NM

6. If Indian, Allottee or Tribe Name

7. Unit Agreement Name

1. Oil Well ☒ Gas Well ☒ Other ☐
DUAL COMPLETION

8. Well Name and No.

BREECH "C" 144-E

2. Name of Operator:

Caulkins Oil Company

9. API Well No.

30-039-24386-00-D1

3. Address of Operator:

(505) 632-1544

P.O. Box 340, Bloomfield, NM 87413

10. Field and Pool, Exploratory Area

BASIN DAKOTA, TOCITO

4. Location of Well (Footage, Sec., Twp., Rge.)

990' F/N 1650' F/W, C SEC. 12-26N-6W

11. Country or Parish, State

Rio Arriba Co., New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Clean-out

TYPE OF ACTION

RECEIVED
SEP 16 1996

OIL CON. DIV.

DISC. 3

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

17. Describe Proposed or Completed Operations:

9-6-96 We intend to pull 2 3/8" tubing from Tocito oil zone.

Then pull 1 1/2" tubing with seal assembly from Dakota zone.

T.I.H. with 1 1/2" tubing with saw-tooth collar on bottom to clean-out over perforations, circulating down with air package to TD at 7647'.

Tocito perforations - 6869' - 6920' Dakota perforations - 7374' - 7593'

A flow tank will be used to recover any produced oil during clean-out.

Following clean-out, 1 1/2" tubing will be re-run to Dakota with re-dressed seal assembly set in packer at 6944' with tubing landed at approximately 7550'.

Then 2 3/8" will be re-run to approximately 6900' for Tocito production.

No new surface will be disturbed, location area will be cleaned up when work is completed.

Estimated starting date - October 7, 1996.

NOTE: The format is issued in lieu of U.S. BLM Form 3160-5

18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT

SIGNED:

Robert L. Verquer
ROBERT L. VERQUER

TITLE:

Superintendent

DATE: 09/06/96

APPROVED

APPROVED BY:

TITLE:

SEP 10 1996
/S/ Duane W. Spencer

DISTRICT MANAGER

CONDITIONS OF APPROVAL, IF ANY

MAOCD