				/
Form 9-331 (May 1963)			5. Lease besignation and serial no. E. W. Mudge #1 SF 078063	
	DRY NOTICES AND REPO form for proposals to drill or to deepen or Use "APPLICATION FOR PERMIT—" for		6. IF INDIAN, ALLOTTEE OR T	RIBE NAME
OIL GAS WE'LL GAS WELL OTHER Water Injection 2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME Carson Unit 8. FARM OR LEASE NAME	
Shell Oil Comp.	9. WELL NO.			
4. LOCATION OF WELL (I See also space 17 belo At surface	32-20 10. FIELD AND POOL, OR WILDCAT Bisti			
2100' FNL & 1880' FEL Section 20			11. SEC, T., B., M., OR BLK. AND SURVEY OR AREA Section 20-T25N-R11W	
14. PERMIT NO.	15. ELEVATIONS (Show when 6429.8 I	• • • •	12. COUNTY OR PARISH 13. San Juan N.	STATE .M.
16.	Check Appropriate Box To Indi	cate Nature of Notice, Report, or C	Other Data ENT REPORT OF:	
TEST WATER SHUT-O FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recomple	REPAIRING WELL ALTERING CASING ABANDONMENT* of multiple completion on Wetion Report and Log form.)	
proposed work. If nent to this work.)	well is directionally drilled, give subsurf: See atta	ace locations and measured and true vertical	depths for all markers and	zones perti

WILL SEND FINAL SUNDRY WHEN LOCATION CLEANED AND READY FOR INSPECTION

cc: NMO&GCC

BISTI WELL P&A WELL NO. 32-20 CARSON UNIT LEASE SHELL OIL COMPANY 6429.8 KB ELEV WESTERN DIVISION NEW MEXICO STATE SAN JUAN COUNTY FROM: 10/12/77

NEW MEXICO BISTI FIELD Carson Unit 32-20 (P&A)

"FR" TD 5020. PB 4910. AFE #571086 provides funds to plug & abandon well. 9/30 RU Bedford & pulled tbg & pkr. 10/1 Ran workstring to PBTD. Circ'd hole w/gel. Spt'd 15 sx cmt plug over & across Gallup perfs. Pulled workstring out of well. Set jacks. 10/3 Shot csg @ 1187'. Spt'd 50 sx cmt plug over csg stub - Pictured Cliffs & Fruitland Coal. Pulled csg to 430'. Spt'd 35 sx cmt plug over 0jo Alamo Sd. Pulled csg to 257'. Spt'd 25 sx cmt plug over sfc csg stub. Pulled csg out of well. Placed 10 sx cmt plug on sfc. Set abandonment marker & RD Bedford.

OCT 12 1977