

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-1434

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME Northeast Bisti Unit
2. NAME OF OPERATOR Texaco, Inc.	8. FARM OR LEASE NAME NEBU
3. ADDRESS OF OPERATOR P.O. Box EE, Cortez, Colorado 81321	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface F-23-25N-11W 1925' FNL & 1915' FWL	10. FIELD AND POOL, OR WILDCAT Bisti Lower Gallup
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA F-23-25N-11W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6513' DF	12. COUNTY OR PARISH San Juan
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco, Inc. plugged and abandoned this well because it was uneconomical to produce. Abandonment procedure commenced 8-8-78. Pulled rods and pump. Tubing stuck at 5008'. Cut off at 5008'. Filled hole with mud. Spotted and squeezed 30 sacks cement across Gallup perms. Perfed 4-way shot at 3900' and squeezed 40 sacks cement across perms. Perfed 4-way shot at 1500' and squeezed 40 sacks cement across perms. Set surface plug of 10 sacks cement and pumped 30 sacks down between 8-5/8" and 5-1/2" casing. Set dry hole marker and cleaned location.

18. I hereby certify that the foregoing is true and correct

SIGNED Alvin M. [Signature] me 26-510TITLE Field ForemanDATE 10-16-78

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____