godense og Ot**Så** Parakterisker <mark>de</mark>ktes

September 14, 1988

Ron Fellows
Area Manager
Bureau of Land Management
Farmington Resource Area
1235 La Plata Highway
Farmington, New Mexico 87401

Subject: Carson Unit Wells

SF-078064 et. al. (WC)

3162.3-2 (019)

Dear Mr. Fellows:

MINERALS GRANCH

BRANCH CHIEF

SOLIDS

FLUIDS D&P _/___

FLUIDS 13.5

FRM

1.3.5-6

1.3.5-6

ALL SUPY

FILES



Reference is made to your letter dated August 15, 1988 concerning Hixon Development Company's plans for eight wells located in the Carson Unit. The Carson Unit Well No. 34-18 is currently awaiting approval from the New Mexico Oil Conservation Division and the Bureau of Land Management to be used as a gas storage well. Upon final approval for this project, work will be commenced to convert the well to a gas storage well.

Hixon Development Company plans to return the Carson Unit Well No. 34-19 to production. A Sundry Notice of intent to return the well to production will be forthcoming.

The remaining six wells addressed in your letter are currently being reviewed as part of an in-depth Carson Unit waterflood and production study. Included in the study are future plans to return additional wells to production and injection as the price of oil increases. With 4.8 million barrels of remaining recoverable oil in the Carson Unit it is important that all existing wellbores be kept available for use as injection and/or producing wells for future waterflooding and enhanced recovery operations.

In addition to the waterflood study, we are also initiating a study of the Fruitland Coal in the Unit. This study is the first step in evaluating the Unit's untapped coal gas potential. The study will be followed by testing of the Fruitland Coal using existing wellbores in the Unit.

SEP 16 1189

THIS APPECTUAL ENGINE

FARET

September 14, 1988 Page 2

Hixon Development Company requests that the last six wells discussed, which are listed below, be kept in their current status until they can be used in the recovery of available

Carson Unit Well No. 31-13 B_{-3} -2.5N+2W SF-C78C64 Status: TA)

Carson Unit Well No. 33-14 W -25N-12W SF-C78C67

Status: TA)

Carson Unit Well No. 44-13 7-3-25N-124 57-078684 Status: (TA)

Carson Unit Well No. 33-15 5-25N-124 5-070:322 Status: OSI as requested by BLM

E-18-25N-11W 14-20-603-1284 Carson Unit Well No. 12-18 Status: OSI as requested by BLM

Carson Unit Well No. 41-19 HStatus: OSI as requested by BLM 19-25N-11W 5F-078063V

Please contact the undersigned at (505) 326-3325 if you have any questions.

Sincerely,

Bruce E. Delventhal

Vice President - Operations

Bruce @ Delventha

BED/das