

October 23, 1981

Gulf Oil Corporation
P. O. Box 670
Hobbs NM 88240

Re: WBU 140 M-27-26N-13W
WBU 166 A-12-15N-13W*

Gentlemen:

Annual packer tests on the above-referenced injection or SWD wells indicate a packer or tubing leak.

In order to insure the protection of hydrocarbon bearing and fresh water zones, you are hearby directed to initiate remedial action within sixty days.

Yours truly,

Jeff A. Edmister
Deputy Inspector

JAE:gc

cc: ~~Operator file~~ *well file*
Prentice Childs
Henry Production Inc.