

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078155

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

West Bisti Unit

8. FARM OR LEASE NAME

9. WELL NO.

166

10. FIELD AND FOOT, OR WILDCAT

Bisti Lower Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 12-T25N-R13W

12. COUNTY OR PARISH

San Juan

13. STATE
NM

1. OIL ☐ GAS ☐ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

Gulf Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)
See also space 17 below.)
At surface

660' FNL & 660' FWL

RECEIVED

FEB

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6256' GL

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Circulate hole with abandonment mud. Spot 100' Class "B" cement plug 2747'-2647' (across Mesa Verde). Spot 100' Class "B" cement plug 1269'-1169' (across Picture Cliffs). Spot 25 sack Class "B" cement plug to surface. Erect P&A marker. Clean and clear location as required. *See attached modifications*



18. I hereby certify that the foregoing is true and correct

SIGNED

R.D. Pitre

TITLE

Area Engineer

DATE

2-10-82

(This space for Federal or State use)

APPROVED BY

CONDITIONS OF APPROVAL

APPROVED

FEB 17 1982

TITLE

DATE

AS AMENDED

for JAMES F. SIMS

DISTRICT ENGINEER

NMOCC

See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
Drawer 600
Farmington, New Mexico 87499-00600

Attachment to Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: 166 West Bisti Unit

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Bureau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. The following modifications to your plugging program are to be made (when applicable):
 - a) spot cement plug from 3716' to 3616'.
 - b) Perforate 5½" casing at 1269' and spot cement plug inside and outside casing from 1269' to 1169'.
 - c) Perforate 5½" casing at 940' and spot cement plug inside and outside casing from 940' to 840'.
 - d) Perforate 5½" casing at 272' and spot cement plug inside and outside casing from 272' to 172'.

Office Hours: 7:30 A.M. to 4:15 P.M.

