

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

## 1. Type of Well

☐ Oil Well
 ☒ Gas Well
 ☐ Other

## 2. Name of Operator

Dugan Production Corp.

## 3. Address and Telephone No.

P.O. Box 420, Farmington, NM 87499 (505) 325 - 1821

## Location of Well (Footage, Sec., T., R., M., or Survey Description)

1000' FSL & 1640' FWL  
Unit letter "N", Sec. 7, T25N, R10W, NMPM

## 5. Lease Designation and Serial No.

NM-8007

## 6. Indian, Allotted or Tribe Name

FEB 2 9 32 AM

## 7. If Unit or CA, Agreement Designation

CA-SW912

## 8. Well Name and No.

Grigsby Federal #2-8

## 9. API Well No.

30-045-21507

## 10. Field and Pool, or Exploratory Area

Basin Dakota

## 11. County or Parish, State

San Juan, NM

## 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

- ☒ Notice of Intent
- ☐ Subsequent Report
- ☐ Final Abandonment Notice

## TYPE OF ACTION

- ☒ Abandonment
- ☐ Recompletion
- ☐ Plugging Back
- ☐ Casing Repair
- ☐ Altering Casing
- ☐ Other

- ☐ Change of Plans
- ☐ New Construction
- ☐ Non-Routine Fracturing
- ☐ Water Shut-Off
- ☐ Conversion to Injection
- ☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

ISOLATE KIRTLAND &amp; OJO ALAMO TOPS

Plan to plug well as follows:

Run cast iron bridge plug and set at 5950' (Dakota Top 6048' with top perforation 6009')

Spot 100' Class B cement plug on top of cast iron bridge plug.

Spot 100' plug across Gallup top at 4977'

Spot 100' plug across Mesaverde top at 2324'.

Spot 200' plug across Pictured Cliffs top at 1445' and Fruitland top at 1352'.

Perforate 50' below surface casing (236') and circulate cement to surface.

## 14. I hereby certify that the foregoing is true and correct

Signed

John Alexander

Title

Vice-President

Date

2/21/2001

(This space for Federal or State office use)

Approved by

Title

Date

FEB 21 2001

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and wilfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

NMOC