Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED
Budget Bareau No. 1004-013:
Expires: March 31, 1993

. Lease	Designation	and	Serial	No.
. Lease	residiración	en en	OCI 141	110.

14-20-603-1431

CONDIN NON	OFO WILD HEL OILLS	OI4 WELLS	
rm for proposals	to drill or to deepen of	r reentry to a differe	nt reservoir.

6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to d Use "APPLICATION FO	rill or to deepen or reentry to a different reserve OR PERMIT—" for such proposals	oir. Navajo Allottees
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Well Other  2. Name of Operator		8. Well Name and No.
Texaco Exploration & Production  3. Address and Telephone No.	Inc.	Navajo Allottees T #2  9. API Well No.
3300 N. Butler, Farmington N.M. 4. Location of Well (Footage, Sec., T., R., M., or Survey D.)	87401 (505)325-4397 Description	30-045-21744  10. Field and Pool, or Exploratory Area Undesignated Farmington
1740' FSL & 1500' FWL Sec. 14- T25N-R11W		San Juan County, New Mexico
12. CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REF	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTIO	NO
Subsequent Reput  SEP 1 5 19  KX Final Abandonment Notice	Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water
Mary Common Comm	in the second se	

Completion or Recompletion Report and Log form i 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled. give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Texaco E. & P. Inc. has Plugged and Abandoned the subject well:

11-12-91. MIRUSU. Lay down rods, pump, & tubing. Set cement retainer @ 699'. Squeezed 25 sx. Class B cement below retainer at 1/2 BPM at 1000#. Sting out & dumped 15 sx. cement on top of retainer. TOC at 550'. Perforated 4 holes at 550' but could not pump up the bradenhead. Reperforated at 400', broke circulation. Pumped 140 sx. Class B Neat cement, circulate to surface. RD and removed surface equipment. during required season.

> Approved as to playging of the wall bern. tion his coals sixed or receive a pro-Participation of the Industry length

		70 171 O 00
£,	0 P	
		Ğ
	51	

I hereby certify that the foregoing is true and correct Signed	Title Area Manager	□A PÝR/®VED
(This space for Federal or State office use)		
Approved by	Title	DatSEP 14, 1992
		ADEA MANAGER