					1	
Form 9-331 (May 1963)			SUBMIT IN TRIPLICATE* (Other instructions on re-	Form approve Budget Bures	ed. 1u No. 42 –R1424	
	DEPARTMEN	DEPARTMENT OF THE INTERIOR (Other instructions on r GEOLOGICAL SURVEY		verse side)	5. LEASE DESIGNATION	AND SERIAL NO.
	GEO			14-20-603-325		
		S AND REPORT of deepen or N FOR PERMIT—" for			6. IF INDIAN, ALLOTTER	C OR TRIBE NAME
OIL K GAS WELL OTHER					7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR					Central Bisti 8. FARM OR LEASE NAM	
Hixon Development Company					СВ11	
3. ADDRESS OF OPERATOR					9. WELL NO.	
P.O. Box 2810, Farmington, New Mexico 87401					73	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' FSL, 1650' FEL, Section 8, T25N, R12W					10. FIELD AND POOL, OR WILDCAT	
					Bisti Lower Gallup	
					11. SEC., T., B., M., OR BLE. AND SURVEY OR AREA	
					Section 8, T2	5N, R12W
	PERMIT NO. 15. ELEVATIONS (Show whet		ether DF, RT, GR, etc.)		12. COUNTY OR PARISH	13. STATE
14. PERMIT NO.						377.6
14. PERMIT NO.		6231' GLE			San Juan	NM
6.			ıte Nature	of Notice, Report, or O		NM NM
6.		oriate Box To Indica	nte Nature			NM
6.	Check Approprofestion	oriate Box To Indica	ate Nature		ther Data	
6.	Check Appropriate of intention	oriate Box To Indica 20:	ate Nature	SUBSEQUA	ther Data	ELL
6. TEST WATER SHUT-OF	Check Appropriate of intention	oriate Box To Indicato: OR ALTER CASING	ate Nature	WATER SHUT-OFF	ther Data ENT REPORT OF: REPAIRING W	TELL SING
6. TEST WATER SHUT-OF	Check Approprotice of intention FF	oriate Box To Indicato: OR ALTER CASING	ate Nature	WATER SHUT-OFF FRACTURE TREATMENT	ther Data ent report of: Repairing w Altering ca Abandonmen	TELL SING
6. TEST WATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE	Check Approprotice of intention FF	oriate Box To Indicator: or alter casing iple complete	ate Nature	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Drilling Pr (NOTE: Report results of	ther Data ent report of: Repairing w Altering ca Abandonmen	TELL SING X

24# K-55 8rd ST&C casing. Set casing at 242.41'. KB is 14'. Cement with 175 sacks, Class "B" cement. Cement circulated to surface. Wait on cement 12 hours. Pressure test BOP and casing to 500 psi for 30 minutes. Held OK. Trip in hole with 7-7/8" bit. Drilled 30' cement. Drill out from under shoe.



		4	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	8. I hereby certify that the foregoing extrue and on	· ·	DATE November 11, 1980
	(This space for Federal or State office use) APPROVED BY	TITLE	DATE
O	CONDITIONS OF APPROVAL, IF ANY:	NMOCG	