

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501.

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
E-289-29

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name Rincon Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Rincon Unit
3. Address of Operator Box 289, Farmington, New Mexico 87401	9. Well No. 131
4. Location of Well UNIT LETTER <u>K</u> <u>1800</u> FEET FROM THE <u>South</u> LINE AND <u>1550</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>27N</u> RANGE <u>7W</u> NMPM.	10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 6552' GL	12. County Rio Arriba


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <u>Repair Casing</u> <input checked="" type="checkbox"/>	OTHER _____ <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To repair a casing failure in this well it is intended to:

- Pull the packer.
- Isolate the leak and squeeze cement the casing.
- Clean out to total depth with gas
- Return well to production.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. G. Bisco TITLE Drilling Clerk DATE 11-28-80

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT #4 DATE DEC 1 1980

CONDITIONS OF APPROVAL, IF ANY: