Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 200

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

about and well. Use form 3160-3 (APD) for such proposals

5.	Lease Serial No.	
	SF-080675	

☐ Temporarily Abandon

■ Water Disposal

Do not use thi abandoned wel	6. If Indian, Allottee	or Tribe Name			
SUBMIT IN TRI		7. If Unit or CA/Agreement, Name and/or No. SAN JUAN 27-4 UNI			
Type of Well	ner		8. Well Name and No SAN JUAN 27-		
2. Name of Operator BURLINGTON RESOURCES OIL & GAS Contact: PEGGY COLE E-Mail: pbradfield@br-inc.com			9. API Well No. 30-039-20383		
3a. Address 3b. Phone No. (include area code) 3401 EAST 30TH Ph: 505,326.9727 FARMINGTON, NM 87402 Fx: 505.326.9563				10. Field and Pool, or Exploratory BS MESA GAL/BASIN DAKOTA	
4. Location of Well (Footage, Sec., T	11. County or Parish	11. County or Parish, and State			
Sec 28 T27N R4W Mer SWS\	RIO ARRIBA C	COUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES)	TO INDICATE NATURE OF	NOTICE, REPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent	☐ Acidize ☐ Alter Casing	☐ Deepen ☐ Fracture Treat	☐ Production (Start/Resume) ☐ Reclamation	☐ Water Shut-Off ☐ Well Integrity	
Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomplete	☑ SUBCOM	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

□ Plug Back

□ Plug and Abandon

6-4-01 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg. TIH w/3 7/8" mill. Blow well & CO. 6-5-01 Blow well & CO. Establish circ. Mill out CIBPs @ 8185' & 8200'. TIH, circ hole clean to PBTD @ 8482'. TOOH w/mill. TIH w/269 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 8437'. (SN @ 8404'). ND BOP. NU WH. RD. Rig released.

Well will produce as a Gallup/Dakota commingle under DHC-2821

☐ Final Abandonment Notice

□ Change Plans

☐ Convert to Injection

14. I hereby certify that the foregoing is true and correct. Electronic Submission #4857 verified For BURLINGTON RESOURCES O Committed to AFMSS for processing	IL & GAS, sent to the Farmington	
Name (Printed/Typed) PEGGY COLE	Title REPORT AUTHORIZER	
Signature THIS SPACE FOR FEDERA	Oate 06/07/2001 OR STATE OFFICE USE	
Approved By	Title	JUL 1 1 2001
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	FARMINGYON FIRE OF AW

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.