UNITED STATES

Dec. 1373	UNITED STATES	5. LEASE		
	DEPARTMENT OF THE INTERIOR	09-000089		
GEOLOGICAL SURVEY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
		Jicarilla Contract #89		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)		7. UNIT AGREEMENT NAME		
		8. FARM OR LEASE NAME Jicarilla E		
1. oil gas well other		9. WELL NO.		
	F OPERATOR roducing TX. & N.M. Inc.	6 10. FIELD OR WILDCAT NAME		
	S OF OPERATOR	Blanco Mesaverde Gas		
	way Pl.,Ste 2700,Houston,Texas 77046	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
helow \	N OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 13, T27N, R	.3W	
AT SURF	AT SURFACE: 990' FNL & 990' FWL		13. STATE	
AT TOP PROD. INTERVAL: Same as surface AT TOTAL DEPTH: Same as surface 3		Rio Arriba	New Mexico	
	Dame ab bullate	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		15. ELEVATIONS (SHOW	/ DE KOR AND WO	
KEI OKI,	ي فغ	7012 GR		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF				
TEST WATER SHUT-OFF				
SHOOT OR ACIDIZE				
REPAIR WELL (NOTE: Report results of multiple, completion or zone				
— (C)				
MULTIPLE COMPLETE CHANGE ZONES OIL COM. COM. DIST 3				
ABANDON* CHANGE ZONES DIST. 3				
(other) Nev				
	BE PROPOSED OR COMPLETED OPERATIONS (Clearly star	te all pertinent details and	s give pertinent dates.	
including	a actimated date of starting any proposed work. It well is (directionally drilled, give bu	bsurface locations and	
measured and true vertical depths for all markers and zones pertinent to this work.)				
4-9-82 Fin Poh w/bit, Blue Jet ran CL 6060-5500, perf Point Lookout 5½ csg, 1 JS/2' in acid 5854-5864, 5868-5878, 5918-5928, 5939-5944, 5950-5958, 5976-5982,				
	In acid 3634-3604, 3606-3676, 3916-3926	mp1 @ 1 PM 4-8-82.	Smith Engr. Co.	
5992-5996, 6017-6021, 37 holes, Job Compl @ 1 PM 4-8-82, Smith Engr. Co. acidize w/2500 gals 15% DINE Acid, 55 RCNBS, bk down Press 1200, treating				
	press 1180-3500, Air 40 BPM, good ball action, ISIP 600, 10 min 500 Blue			
Jet ran junk bskt knocking off ball sealers, Smith Engr Co frac perfs 5854-				
6021 w/92.400 gals slick wtr, 72,400# 20/40 sd, press on 20,000 gals pad				
	1400 @ 62 BPM, treating press on 1# sd 1100-1300 @ 61 BPM ISIP 700, 15 min			
300. Job Compl @ 5:30 PM, 4-8-82.				
4-14-82	F thru sep on 16/64 ck, TP 600, GV 60	1 MCFD, rec 43 BLW	& trace of oil/5	
	hrs, kill well w/40 bbls wtr, POH w/pkr, Blue Jet set Baker 5½" RBP @ 5800			
	test RBP w/2800 psi OK, Blue Jet perf	oz csg in Clill not	nerf Monefee form	
	2' @ 5508-12, 5529-33, 5538-48 & 5552-6	oo, to notes, then	(Cont'd on back	
Subsurface S	Safety Valve: Manu. and Type	Se	t @ Ft.	
18. I hereby certify that the foregoing is true and correct				
SIGNED Paular a Collins TITLE Authorized Agent DATE 4-26-82				
(This space for Federal or State office use)				
TITLE				
APPROVED BY	OF APPROVAL IF ANY:	aggestish i	- B 12002D	