

F

30-039-24038

5-19-86

F. Loc. 790/N; 1190/W Elev. 7141 GL Spd. Comp. TD PB
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @
 Csg. Perf. Prod. Stim.

T Gas
R
A
N
S

BO/D Grav. 1st Del. Gas
 MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS		NiTD X	Well Log	TEST DATA						
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House		Acres W/320								
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

P
o
o

Blanco MV Co. RA S 22 T 27N R 4W U D Oper. EPNG CO.

SJ 27-4 Unit No. 149A

SJ 27-4 Unit #149A

D-22-27N-4W

Meridian Oil Inc.

Caller Service 4104
Farmington, New Mexico 87499

JUN 22 1987

CERTIFIED--RETURN RECEIPT REQUESTED
P-488-625-124

Meridian Oil Incorporated
P.O. Box 4289
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

1. No. 92A San Juan 30-6 Unit, NW/4SE/4 sec. 33, T. 30 N., R. 7 W., Rio Arriba County, New Mexico, on lease NM-02151-R.
2. No. 403 San Juan 30-6 Unit, NE/4NW/4 sec. 23, T. 30 N., R. 7 W., Rio Arriba County, New Mexico, on lease SF-079382.
3. No. 404 San Juan 30-6 Unit, NW/4NE/4 sec. 23, T. 30 N., R. 7 W., Rio Arriba County, New Mexico, on lease SF-079382.
4. No. 407 San Juan 30-6 Unit, SE/4NW/4 sec. 14, T. 30 N., R. 7 W., Rio Arriba County, New Mexico, on lease NM-012573.
5. No. 18A San Juan 27-4 Unit, SW/4NW/4 sec. 4, T. 27 N., R. 4 W., Rio Arriba County, New Mexico, on lease SF-080663.
6. No. 134A San Juan 27-4 Unit, NE/4NW/4 sec. 9, T. 27 N., R. 4 W., Rio Arriba County, New Mexico, on lease SF-080668.
7. No. 138A San Juan 27-4 Unit, SW/4NE/4 sec. 16, T. 27 N., R. 4 W., Rio Arriba County, New Mexico, on lease SF-080674.
8. No. 149A San Juan 27-4 Unit, NW/4NW/4 sec. 22, T. 27 N., R. 4 W., Rio Arriba County, New Mexico, on lease SF-080674.

The subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

RECEIVED
JUN 23 1987
OIL CON. DIV.
JUN 3

ABANDONED LOCATIONS

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in an assessment for noncompliance.

Sincerely,

/s/ John L. Keller

FOR Ron Fellows
 Area Manager

3 Enclosures

cc:
NMOCD (2)