

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER</p> <p>2. NAME OF OPERATOR Texaco Inc.</p> <p>3. ADDRESS OF OPERATOR P.O. Box EE, Cortez, CO. 81321</p> <p>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1450' FNL & 1450' FWL</p> <p>14. PERMIT NO.</p>	<p>5. LEASE DESIGNATION AND SERIAL NO. NM-16473</p> <p>6. IF INDIAN, ALLOTTEE OR TRIBE NAME</p> <p>7. UNIT AGREEMENT NAME</p> <p>8. FARM OR LEASE NAME Hanlad Federal</p> <p>9. WELL NO. 1</p> <p>10. FIELD AND POOL, OR WILDCAT Nipp Pictured Cliff</p> <p>11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.31, T26N,R12W</p> <p>12. COUNTY OR PARISH 13. STATE San Juan NM</p>
<p>15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6145' GR</p>	

RECEIVED

SEP 13 1985

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco Proposes to abandon this well using the following procedure, subject to managerial approval. Approval of this procedure should be granted within 90 days. Prior to initiating plugging operations your office will be notified so that a representative can witness.

Procedure:

- 1.) MIRUSU, TIH 1 1/2" tubing to PBTD (1251').
- 2.) Rig up cement pump trucks to tubing. Spot 16 sxs of class B neat cement. TOOH w/tubing.
- 3.) Rig up cement pump trucks to casing. Pump 34 sxs of class B Neat cement. Squeeze perfs & Leave casing full to surface.
- 4.) Erect P & A Marker and clean and reseed location.

RECEIVED
SEP 23 1985
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED *John R. Mang*

TITLE **AREA SUPT.**

APPROVED

DATE **9/12/85**

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE **SEP 19 1985**

John R. Mang
AREA MANAGER
FARMINGTON RESOURCE AREA

BLM (5) - NMOGCC (3) - JNH-AJS-ARM

*See Instructions on Reverse Side

NMOGCC