UNITED STATES	5. LEASE	
DEPARTMENT OF THE INTERIOR . /	14-20-603-2085	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	Navajo	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plue back to a different	7. UNIT AGREEMENT NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME	
1. oil 😝 gas 🗍	Old Trading Post	
well Well cther	9. WELL NO.	
2. NAME OF OPERATOR	3	
DOME PETROLEUM CORP.	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR 501 Airport Drive,	Bisti-Lower Gallur	
Suite #114, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
<ol> <li>LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below.)</li> </ol>	Sec. 9, I26N, R14W	
AT SURFACE: 2310' FSL, 330' FEL	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL:	San Jaun New Mexico	
AT TOTAL DEPTH:	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KCB, AND WD)	
DECLIEST FOR ARRESONAL TO: CURSEOUTAL REPORT OF	6051' GR	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	of-19	
FRACTURE TREAT	(NOTE: Report regults of multiple completion or one	
PULL OR ALTER CASING [ ] [ ]  MULTIPLE COMPLETE [ ] [ ]	change of Form 19802 6 1981	
CHANGE ZONES	OIL CON. COM.	
A6ANDON*	DIST. 3	
(other) Back Filled Reserve Pits	6,01,0	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen	irectionally drilled give subsurface ocations and	
Back filled reserve pits as per your instruction completed on 10/16/81.	ons 9/28/81. Work	

Subsurface Safety Valve: Manu. and Typ	oe	Set	@ Ft.
18. I hereby certify that the foregoing is	true and correct		
SIGNED All Heigh Sworth	TITLE Area Prod.	Supt. DATE October	21, 1981
	(This space for Federal or St.	ate office use)	
APPROVED BY	TITLE -	DATE	
•			

\*See Instructions on Reverse Side

RS