

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
Jicarilla Contract #241

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Boulder

9. WELL NO.

43-23

10. FIELD AND POOL, OR WILDCAT

Boulder Mancos

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

Sec. 23, T28N, R1W, N4PM

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Socoxy Mobil Oil Company, Inc.

3. ADDRESS OF OPERATOR
P. O. Box 778, Farmington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface
1650' from So. line & 990' from E. line of Sec. 23, T28N, R1W, N4PM

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
7247' OR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF :

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Fraced well w/lease crude 5/19/63 and completed pumping load oil on 5/20/63. Recovery of frac declined to 1 Bbl./day with approximately 450 Bbls. left to recover. It is proposed to abandon this well by 2/1/64, (weather permitting) by the following procedure:

1. Pull rods and tubing. Kill Mancos Zone with water.
2. If 4 1/2" liner is recovered, plug 7" shoe with cement 100' in and 100' out (2525'/2725'). If 4 1/2" liner is not recovered, plug across 7"x4 1/2" lap with 200' plug (2467'/2667').
3. If 7" casing is recovered, plug 7" stub with cement 50' in and 90' out.
4. Set bridging plug at 25' in 9-5/8" casing. Fill to surface with construction cement. Erect monument.
5. Salvage wellhead equipment.
6. Clean location.

RECEIVED

DEC 9 1963

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

RECEIVED
DEC 10 1963
OIL CON. COM.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED M. J. Meyer TITLE Sup. Instruction Foreman DATE 12/6/63

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

