


Form 9-331a
(March 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Jicarilla Apache**
Indian Reservation
Lease No. _____
Unit **Contract No. 24**
South Dulee

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO REPAIR WATER SHUT-OFF		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 11, 19**52**

Well No. **1** is located **330** ft. from **N** line and **330** ft. from **E** line of sec. **6**
Center 33x 33x Sec 6 **24N** **24E** **10W**
 (4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Will Cat (South Dulee) **Alto Arriba** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the ~~datum~~ **ground** above sea level is **7100** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is proposed to leave mud in ~~the~~ bottom of hole, cement below 9 5/8" casing with 100 sack cement to bring cement up into 9 5/8" casing. Leave mud in casing and spot cement plug below Mesa Verde at 5,792' and test for oil or gas.

SLP-COM
USGS(a)-JOS(a)-COO(a)-file

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Continental Oil Company**

Address **Shiprock, New Mexico**

By 

Title **Area Foreman**