SF017382

6. IT INDIAN, ALLOTTEE OR TRIBE NAME

5. H ASI

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

| SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for projectals to drift or to deepen or plux back to a different receiver, Use Form 9-111 (C for such projectals.)  1. oil gas X; well other  2. NAME OF OPERATOR  E1 Paso Natural Gas Company  3. ADDRESS OF OPERATOR  P. O. Box 990, Farmington, N. M. 87401  4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below.)  AT SURFACE: 990¹/S, 1800¹/E, Sec. 9, T27N,R10W AT TOTAL DEPTH: Same TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES | 7. UNIT AGREEMENT NAME  8. FARM OR LEASE NAME.  SE 077382 Hargrave  9. WELL NO.  2  10. FILLD OR WILDCAT N/ ME Fulcher Kutz  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SE Sec. 9, T27N, R10W  12. COUNTY OR PARISH 13. STATE San Juan New Mexico  14. ACL NO.  15. ELEVATIONS (SHOW DE, KDB, AND WD) 6344 DF  (NOTE: Report results of multiple completion or zone change on Form 9-130.) |
|--|--|
| ABANDON* (other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is discussive and true vertical depths for all markers and zones pertinen.  1. Plug well because it is uncapable of product. Pull tubing and casing.  3. Use 50 sx. cement to set plug across Picture. Use 50 sx. to put plug across casing stub.  5. Use 50 sx. to put plug across open hole.  6. Use 10 sx. for surface plug.  7. Set dry hole marker.  8. Clean up location.   | rectionally drilled, give subsurface locations and to this work.)*  cing.  |
| Subsurface Safety Valve: Manu. and Type  | Set @  |
| 18. I hereby certify that the foregoing is true and correct  |  |

RECEIVED

NOV 22 1977

de

CONDITIONS OF APPROVAL, IF ANY:

"See Instructions on Reverse Side

THILE Production CATE November 22, 1977
Engineer

(This space for Federal or State office use)

U.S. Geological Schay Farmington, N.M.