Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED BIM

FORM APPROVE

OMB No. 1008	
Expires July 31	<u>. 1</u> 99

SUNDRY NOTICES AND REPORTS ON WELLS 99 MAR 22 P	H
---	---

Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) to	or such proposition FARMINGHON	NM
SUBMIT IN TRIPLICATE - Other instruction	ons on reverse side	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Oil Well Gas Well Other	APR - 8 1999	8. Well Name and No.
2. Name of Operator Louis Dreyfus Natural Gas Corp.	anido Lour	9. API Well No. 30-045-06650
Suite 600, Oklahoma City, OK 73134 (405) 740 50287 DEST	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1650' FSL & 990' FEL		West Kutz, P.C. 11. County or Parish, State
NE SE Sec. 7-T27N-R11W	IDICATE NATURE OF NOTICE RE	San Juan Co., NM

12. CHECK ATTROTRITE BOTILES, TO STATE	
SURMISSION	TYPE OF ACTION

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclarnation Recomplete Temporarily Abandon Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof Describe Proposed of Completed Operation (clearly state an pertunent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Work commenced 2/3/98. Cleaned out wellbore to TD of 1924'. Ran 44 jts. 4" 10.46# csg, set @ 1891'. Pumped 150 sks. 50/50 POZ C1. "B" cmt. w/4% gel, 3% gilsonite, 2% CaCl. Circulated to surface. Drilled out cmt. to PBTD of 1880'.

Perforated 1802'-1810', 2 SPF, 16 holes and 1830'-1850', 2 SPF, 40 holes. Total 56 holes. Acidized w/1000 gal. 15% HCL. Frac w/700 N2 foam; used total of 446,000 SCF N2, 104,700# 20/40 Arizona sand and 10,760# 20/40 SDC.

Set 2 3/8" 4.7# J-55 tbg. @ 1845'. Put well on pump (2" x 1 1/4 x 6' x 4'). Set pumping unit, separator, compressor, and tank. Turned well to sales line 3/6/98.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Property 14. Title		-nicion
Signature Dat	gulatory Tech e 17/99	nnician
THIS SPACE FOR FEDERAL O	R STATE OFFICE	USE
Approved by	Title	Date ACCEPTED FOR RECORD
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.		APR 0.5 1999