

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

RECEIVED
2001 JUN 21 PM 3:58

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

ENERGEN RESOURCES CORPORATION

3a. Address

2198 Bloomfield Highway, Farmington, NM 87401

3b. Phone No. (include area code)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1450' FSL, 1450' FEL, sec 1, T 27 N, R 9 W NMPM

5. Lease Serial No.

I-149-Ind-8463

6. If Indian, Allottee or Tribe Name

Navajo allotted

7. If Unit or CA/Agreement, Name and/or N

8. Well Name and No.

Candelario ET. A1. 1

9. API Well No.

30-045-06809

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

San Juan N.M.

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☒ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

6/1/01 MIRU. ND wellhead, NU BOP.

6/2/01 TOH laying down 193 jts 2-1/16" tubing. PU RBP, packer & 2-3/8" tubing. Set RBP at 6200', set packer at 6170' & test RBP to 500 psi. Test casing to 1000 psi - OK.

6/4/01 Lower tubing, latch onto RBP & TOH with packer & RBP. TIH with 2-3/8" tubing, tag at 6507', clean out to 6620'. Land tubing at 6533', seating nipple at 6501'. ND BOP, NU wellhead.

6/5/01 Acidize with 1000 gals 15% HCL acid. RDMO.



14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Don Graham

Title

Drilling/Completion Foreman

Date

6/19/01

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

JUL 10 2001

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

MN

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC