

F

30-045-27388

6-26-89

F. Loc. 1710/S; 1370/W Elev. 6210 GL Spd. \_\_\_\_\_ Comp. \_\_\_\_\_ TD \_\_\_\_\_ PB \_\_\_\_\_  
 Cu. ft. Cu. ft. Cu. ft.  
 Casing S. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Int. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Pr. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. T. \_\_\_\_\_ @ \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Prod. Stim. \_\_\_\_\_

T Gas  
R  
A  
N  
S

BO/D Grav. \_\_\_\_\_ 1st Del. Gas \_\_\_\_\_  
 I.P. \_\_\_\_\_ MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil \_\_\_\_\_

TOPS		NTD	X	Well Log	TEST DATA						
Ojo Alamo		C-103	/	Plat X	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-104		Electric Log							
Fruitland				C-122							
Pictured Cliffs		Ditr		Dfa							
Chacra		Datr		Dac							
Cliff House		<div style="text-align: right;">32.0 W/302 Acres</div>									
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											

P  
o  
o

BasinFrCoal Co. SJ S 9 T 27N R9W UK Oper. Southland Royalty Co. Lse. Whitley

No. 282

Whitley #282

K-9-27N-9W

SOUTHLAND ROYALTY CO.



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA  
1235 LAPLATA HIGHWAY  
FARMINGTON, NEW MEXICO 87401



IN REPLY REFER TO:

NM-02294 (WC)  
3162.3-1(F) (019)

Southland Royalty Co.  
P.O. Box 4289  
Farmington, NM 87499

JUL 02 1991

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 282 Whitley, SW/4 sec. 9, T. 27 N., R. 9 W., San Juan County, New Mexico, lease NM-02294. As discussed with Peggy Bradfield of your company, the subject APD is rescinded and returned due to drilling not being commenced within two years of the approval date. (two extensions approved)

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

FOR John L. Keller  
Chief, Branch of Mineral Resources

Enclosure

cc:  
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

**RECEIVED**  
JUL 03 1991  
OIL CON. DIV.  
DIST. 3

**ABANDONED LOCATION**