

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

RECEIVED
BLM

Sundry Notices and Reports on Wells

070 FARMINGTON, NM

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

295' FSL, 560' FWL, Sec.7, T-27-N, R-9-W, NMPM

5. Lease Number
SF-077874

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Hanks #5R

9. API Well No.
30-045-29551

10. Field and Pool
Fulcher Kutz PC

11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	

13. Describe Proposed or Completed Operations

6-21-99 MIRU. ND WH. NU BOP. TIH, tag up @ 2260'. Circ hole clean. PT csg to 500 psi, slow leak @ 500# - 100#. Plug #1 w/tbg @ 2260' w/23 sx Class "B" neat cmt. Displaced @ 2260-1705'. TOOH w/tbg to 1708'. SDON.

6-22-99 Tag cmt @ 1711'. TOOH w/tbg to 1360'. Plug #2 w/tbg @ 1360' w/13 sx Class "B" neat cmt. Displaced @ 1360-1046'. TOOH w/tbg to 997'. Circ hole clean w/8 bbl; light colored cmt returns. WOC. TOOH w/tbg to 701'. Plug #3 w/tbg @ 701' w/16 sx Class "B" neat cmt. Displaced @ 701-314'. TOOH w/tbg. WOC. PT csg to 500 psi/5 min, OK. TIH w/wireline tag plug, perf 3 sqz holes @ 140'. TOOH w/wireline. Plug #4 w/40 sx Class "B" neat cmt circ dwn 3 1/2" csg & out bradenhead. 1 bbl good cmt in return. ND BOP. Remove WH. Install P&A marker w/10 sx Class "B" cmt. RD. Rig released.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 6/30/99

vkh

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

NMOCD

JUL 30 1999