(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4. Approval expires 12-31-60.

Land Office Santa Fe

Lesse No. SF 047039 C

Unit SW/4 Sec. 18, T-28N
R-10W, N.M.P.M.
San Juan County, New Mercico

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALI'ER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHI	ECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
	November 28, 1961 , 1961
Lachman 'ell No. 3/ is located 990	ft. from. ${\mathbb{Z}} $ line and 990 ft. from ${\mathbb{Z}} $ line of sec. 18
SW/4 Sec. 18 281	N 10-W N.M.P.M. (Range) (Meridian)
(1/2 Sec. and Sec. No.)	San Juan County New Realton
Fulcher-Kutz	(County or Subdivision) (State or Territory)
he elevation of the derrick floor above	
	DETAILS OF WORK
itate names of and expected depths to objective sand	ds; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement te, and all other important proposed work)
	ds; show area, weights, and the proposed work) ts, and all other important proposed work)
Set 10 sacks cement plug in $4\frac{1}{2}$ Shot casing off at 1157. Pull set 55 sacks cement plug inside to 10 sacks cement plug in to Erected regulation marker, cle	pipe over perfs 1930-1970. Led 1157' of casing. Filled hole with mud. Le stub and open hole from 1120-1170. Le pop of surface pipe. Leaned location.
Tunderstand that this plan of work must receive	pipe over perfs 1930-1970. ded 1157' of casing. Filled hole with mud. de stub and open hole from 1120-1170. op of surface pipe. eaned location. DEC1 ON. CON. CON. CON. DEC7. Separation of the companies.
et 10 sacks cement plug in 42 thot casing off at 1157. Pull set 55 sacks cement plug insidet 10 sacks cement plug in to brected regulation marker, cle	pipe over perfs 1930-1970. ded 1157' of casing. Filled hole with mud. de stub and open hole from 1120-1170. op of surface pipe. eaned location. DEC1 ON. CON. CON. CON. DEC7. Separation of the companies.
lunderstand that this plan of work must receive Company CONCRESS OIL COM	pipe over perfs 1930-1970. ded 1157' of casing. Filled hole with mud. de stub and open hole from 1120-1170. op of surface pipe. eaned location. DEC1 ON. CON. CON. CON. DEC7. Separation of the companies.
Set 10 sacks cement plug in 42 Shot casing off at 1157. Pull Set 55 sacks cement plug insid Set 10 sacks cement plug in to Erected regulation marker, cle	pipe over perfs 1930-1970. ded 1157' of casing. Filled hole with mud. de stub and open hole from 1120-1170. op of surface pipe. eaned location. DEC1 ON. CON. CON. Supproval in writing by the Geological Survey before operation only be compansed.