

1-Redfern
1-Boffora
1-Boese
1-file


ILLECIBLE

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. N.M. 021116
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 4, 1958


Well No. 4 is located 1980 ft. from NE line and 1010 ft. from E line of sec. 16
(S) (W)
NE 1/4 Sec 16 (Twp.) 11N (Range) 10W (Meridian)
Midland (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the Ground level above sea level is 5592 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 7-10-58 Drilled 1 1/2" hole to 190' ran 7 jts 10-3/4" ong. 12 188.36' set @ 171.74 cemented w/150 sz reg. Drilled 9-3/8" hole to 4175' ran 7-5/8" ong set @ 4173 cemented w/200 sz w/151 tool @ 1706 cm w/200 sz. Drilled 6-3/4" hole to 6270' ran 3 1/2" 154# 4-55 ong set @ 6266 cemented w/150 sz.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Redfern & Markham

Address Box 1747

Midland, Texas

By Original signed by [Signature]

Title Consulting Engineer