Form 9-331 (May 1963)

SHOOT OR ACIDIZE

REPAIR WELL

UNITED STATES SUBMIT IN TRIPLICATE* (Other instructions on reverse side) Form approved. Budget Bureau No. 42-R1425. LEASE DESIGNATION AND SERIAL NO.

ABANDON*

CHANGE PLANS

SHOOTING OR ACIDIZING

(Other) Tubing and Cl

Form approved. Budget Bureau No. 42-R1424.

GEOLOGICAL SURVE	SF 0711
SUNDRY NOTICES AND REPORT (Do not use this form for proposals to drill or to deepen or Use "APPLICATION FOR PERMIT—" for	plug back to a different reservoir. such proposals.)
OIL GAS OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
El Faso Catural Gas C	Tooltov 9. well no.
3. ADDRESS OF OPERATOR 4. LOCATION OF WELL (Report location clearly and in accordance with See also space 17 below.)	Ith any State requirements.* 10. FIELD AND POOL, OR WHIDCAT NA VILL MEAN WHICH HAD POOL OR WHIDCAT
1660 S 1825 W	Sec. 26-28-29
14. PERMIT NO. 15. ELEVATIONS (Show wh	ether DF, RT, GR, etc.) 12. COUNTY OR PARISH 13. STATE
6627 Gr.	San Juan II. M.
16. Check Appropriate Box To India	cate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING FRACTURE TREAT MULTIPLE COMPLETE	WATER SHUT-OFF REPAIRING WELL FRACTURE TREATMENT ALTERING CASING

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3256' of 1" I.J. tubing with gas lift valves @ 2931and 3095 was run as siphon and production tubing in the 2 7/8" slim hole.



1)		
18. I hereby certify that the foregoing is true and correct SIGNED	TITLE Production Engineer	DATE _August 15, 1972
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE