Form 3160-5 June 1990)

representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals		5. Lease Designation and Serial No. SF 077085 6. If Indian, Allottee or Tribe Name	
		7. If 'Unit or CA, Agreement Designation	
1. Type of Weil Oil Gas Weil Other		8. Well Name and No. Omler A 12	
2. Name of Operator	Attention:	9, API Well No.	
Amoco Production Company 3. Address and Telephone No.	Lois Raeburn	3004525303	
P.O. Box 800, Denver, Colorado 80201 (303) 830-5294		10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Chacra	
•		11. County or Parish, State	
1110FNL 1550 FEL Sec.	. 36 T 28N R 10W	San Juan New Mexic	0_
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTIO		
Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly state all pertinent subsurface locations and measured and true vertical depths for all ma	Recomp t details, and give pertinent dates, including estimated date of sta	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water Report results of multiple completion on Well Completion or eletion Report and Log form. }	
Amoco Production Company request permissi See attached procedures. If you should have any questions please conta	ion to Plug and Abandon the above mention	SEGETAL 84 SES -1 BH 1: 18 87 SESTANDON' NW	
14. I hereby certify that the foregoing is true and correct Signed An Alloward	Title Business A	Assistant Date 08-29-1994	=
(This space for Federal or State office use)			
Approved by Conditions of approval, if any:	Title	APPROVED	_
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly	and willfully to make to any department or agency of the United	States any false, ficticious, or fraudulent statements or	

PXA Procedures Omler A #12

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 1 1/4" tbg and lay down. RIH with 2 3/8" workstring and cement retainer, set retainer at 3036'. Test casing integrity to 500#. Squeeze perfs at 3086' to 3098' with 8.689 cuft cement.
- 4. Pull out of retainer and spot cement plug to surface with 407.583 cuft cement.
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

OMLER A 012

Location - 36B-28N-10W

SINGLE ck

Orig.Completion - 6/82

Last File Update - 1/89 by BCB

