Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 20

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					Expires: November 30, 2000		
					5. Lease Serial No. SF-077967		
					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well					8. Well Name and No. GALLEGOS CANYON UNIT 72		
2. Name of Operator Contact: CHERRY HLAVA					9. API Well No.		
BP AMERICA PRODUCTION	E-Mail: hlavacl@t	Dbp.com		30-045-07039			
3a. Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700			10. Field and Pool, or Exploratory BASIN FC & KUTZ PC, WEST			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State		
Sec 36 T28N R13W SWNE 1730FNL 1650FEL					SAN JUAN COUNTY, NM		
12. CHECK APPE	ROPRIATE BOX(ES) T	O INDICATE N	ATURE OF	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION						
- Notice of Johnson	☐ Acidize	☐ Deeper	☐ Deepen		tion (Start/Resume)	☐ Water Shut-Off	
☐ Notice of Intent	☐ Alter Casing	☐ Fractur	☐ Fracture Treat		ation	☐ Well Integrity	
Subsequent Report	□ Casing Repair	□ New C	☐ New Construction		olete	⊠ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon		☐ Temporarily Abandon		Subsurface Commingli	
	☐ Convert to Injection	Plug B	☐ Plug Back		Disposal	**5	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f On 11/30/01 Amoco Productic pool and commingle productic 12/7/01. Work completed 3/27/02 and	bandonment Notices shall be f inal inspection.) on Company requested p on downhole with the exi	iled only after all req permission to re-e sting Basin Fruitli	uirements, incluenter the Kutz	ding reclamatio	n, have been completed, a	0-4 shall be filed once and the operator has	
Please see attached subsequent report.							
14. I hereby certify that the foregoing is	s true and correct. Electronic Submission For BP AMERICA F						
Namc (Printed/Typed) CHERRY	Hlave 1	Title AUTHORIZED REPRESENTATIVE					
Signature (Electronic	Submission)	1	Date 04/02/	2002			
	THIS SPACE F	OR FEDERAL	OR STATE	ALL SEP	ED FOR RECOR	D	
				1.202.			
_Approved_By			Title	AF	PR 1 2 2002 atc	-	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office	FARMI	NGTON FIELD OFFIC	E 15	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					2ko o an) departitient of	agency of the United	

GALLEGOS CANYON UNIT # 72 DHC SUBSEQUENT REPORT 04/02/2002

- 03/12/02 MIRUSI Take Readings, TBG 0 PSI; Csg 0 PSI; BH 0 psi. Press up tbg to 300 psi. held ok. TOH w/rods. SDFN
- 03/13/02 NDWH, NUBOP, TIH & mill out CIBP @ 1438'. Pull above perfs. SDFN.
- 03/14/02 Clean out to plug, drill out cmt to 1470'. TOH w/ DC's & mill. TIH w/pkr & set plug about 50' above perfs. SDFN.
- 03/15/02 TOH w/pkr; TIH; TOH w/RBP. TIH w/new RBP & set @ 1300'. TOH w/tbg & ret. head. TIH & set pkr above RBP & press tst to 1000#. Plg held press ok. TOH w/pkr; Isolate hole in csg f/80' to 114'. TOH w/rest of tbg & drop snd on RBP. SI FN
- 03/18/02 RUSU & pmp 14 B.W. to establish circ. to surface. Pmp'd 10 bbls F.W. Pmp'd 70 sxs cl G cmt; density 15.80 ppg; yield 1.160 cuft. & circ. 2 bbls cmt to surface. SI B.Head & press B. Head to 110# & press drop to 85#. RD MO SU.
- 03/19/02 Pressure tst squeeze job to 500 psi. Lost 150 lbs in 5 min. Found leak on a 2" release valve, chng out & retest to 300 lbs, held ok. TIH w/5 ½" scraper to 180'. TOH, TIH w/4 ¾" bit & circ snd off RBP; pull up & unload hole w/air, TOH w/bit, TIH w/Ret head, set on top of RBP & blow hole clean with air. TOH w/RBP. TIH w/4 ¾" bit & tag 30' fill. C/O to 1480'. SDFN.
- 03/20/02 Clean out
- 03/21/02 Clean out to PBTD @ 1455'. Flow back on own.
- 03/22/02 Clean out
- 03/25/02 Cleaning out
- 03/26/02 Readings csg 135 psi;BH 25 psi. TIH tag 15' fill. Clean out to TD. Flw back gas, light mist & snd. Ran sweeps.
- 03/27/02 Reading 130 psi csg. 35 psi BH. Clean out to TD. TIH & land tbg @1461.32'.

 TIH w/27 rods. TOH. LD. TIH w/pmp, 56x3/4" rods, 8' & 4' subs. Space out pmp, seat it. Pres tst pipe to 500 psi. check pmp action, tst ok. Hang on rods. RDSU & Equip. MO location.
- 03/28/02 Well is down hole commingling FC & PC. No new perfs. were added.