BHP

RESIDED

RESIDE

RESIDED

RESIDE


RESIDED

June 22, 1994

CERTIFIED - RETURN RECEIPT REQUESTED P 226 454 411

Bureau of Land Management Farmington District Office 1235 LaPlata Highway Farmington. New Mexico 87401 ATTN: MR. WAYNE TOWNSEND

Dear Sir:



- 1. GCU #41 Included in the 1994 POD and will be recompleted to the Fruitland Coal during this fiscal year. 5F-0793×6A
 32-29N-/24
- 2. GCU #7 Recompleted from the Pictured Cliffs to the Fruitland Coal in May 1992 and is currently waiting on pipeline connection. I-149-Ind-9470 30-28N-12W
- 3. GCU #267 Inadvertently overlooked and not included in the 1994 POD for the unit. A review of the completion history and open hole logs indicates that this well is an excellent candidate for restimulation in the Pictured Cliffs interval. Therefore, an amended POD will be submitted to include this well.

 \$\int_{F-07890F} 23-28N-12\omega\$

If you have any questions or need additional information, please contact me directly at (713) 961-8423.

Sincerely, Colle

Carl Kolbe

Regulatory Affairs Representative

THIS APPROPRIE EXPENSES THE 0.1 1995_

NMOCD

APPHOVED JUL 06 1994

Americas Division BHP Petroleum