

(SUBMIT IN TRIPLICATE)

Indian Agency

Bureau

Allotted

Allottee

Lease No.

1-149-NE-2473

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
Report of Accident	X		

RECEIVED  
DEC 30 1963  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Collage Canyon Unit

Farmington, New Mexico December 27, 1963

Well No. 120 is located 120 ft. from [N] line and 730 ft. from [E] line of sec. 25

NE/4, NE/4 Section 25  
(1/4 Sec. and Sec. No.)T-20N  
(Twp.)R-13W  
(Range)N.M.P.M.  
(Meridian)On On Gallup  
(Field)San Juan  
(County or Subdivision)New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 5000 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On December 21, 1963 at approximately 11:00 A.M., a fire occurred at the tank truck at the above well. This fire completely destroyed one B-53 Mack truck with a 2100 gallon tank mounted on it, owned by Alton E. Lee, Inc., and one Cardwell "T" double drum well servicing unit mounted on a 1954 International truck owned by Artec Well Servicing Company. Arza Whitson, an employee of Alton E. Lee, Inc., died as a result of burns received. Lawrence Thompson, an employee of Artec Well Servicing Company, suffered third degree burns on his right forearm. These burns were as a result of Thompson's efforts to extinguish the flames on Whitson.

There was no well fire involved or damage to surface equipment.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations can be commenced.


Company PAN AMERICAN PETROLEUM CORPORATION

Address P. O. Box 480

Farmington, New Mexico

By

Title Area Superintendent



1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000