

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-077966

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Gallegos Canyon Unit

8. FARM OR LEASE NAME

Gallup Part. Area "C"

9. WELL NO.

112

10. FIELD AND POOL, OR WILDCAT

Cha Cha Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 23-T28N-R13W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Amoco Production Company - operator

Aztec Oil & Gas Company - sub-operator

3. ADDRESS OF OPERATOR

Amoco - Security Life Building, Denver, Colorado 80202

Aztec - 2000 First National Bank Bldg., Dallas, Texas 75202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1980' SL, 775' EL, Section 23-28N-13W

Unit Letter I

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5859 KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF* ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Status: 8-5/8" surface pipe to 212'. Base of Ojo Alamo 270'. DV tool @ 1765'.
Perforations 5519-24. 4-1/2" casing in 7-7/8" hole. Depleted oil well.

Propose to plug well as follows:

1. Fill hole with gel-mud. Place 10 sxs. cement (130") plug from 5524' to 5394'
2. Place 10 sxs. cement (130') plug from 1830' to 1700'
3. Cut 4-1/2" casing at free point (top annular cement calculated 626') and pull same. Fill hole with gel mud. Place 30 sxs. cement (160') plug bottomed 75' below casing cut.
4. Place 40 sxs. cement (137') plug from 300' to 163'
5. Place 10 sxs. cement (37') plug in top of surface pipe.
6. Cut off pipe at bottom of cellar, place one sack cement on top of pipe and install regulation marker.
7. Clean up and level location to as near original contour as practicable.

AMOCO PRODUCTION COMPANY

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: