

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ GAS ☒ OTHER ☐
2. NAME OF OPERATOR
Amoco Production Co.
3. ADDRESS OF OPERATOR
2325 E. 30 St., Farmington, NM 87401
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 1010' FNL x 1675' FEL
14. PERMIT NO.
15. ELEVATIONS (Show whether on surface or subsurface)
5656' KB

5. LEASE DESIGNATION AND SERIAL NO.
SF-078904
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
Gallegos Canyon Unit
8. FARM OR LEASE NAME
9. WELL NO.
243
10. FIELD AND POOL, OR WILDCAT
Basin Dakota
11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA
NW/NE Sec 24, T28N, R12W
12. COUNTY OR PARISH
San Juan
13. STATE
NM

RECEIVED
DEC 22 1986

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANE ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☒
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

As discussed between Bruce Williams of Amoco and Steve Mason, the request to repair the Gallegos Canyon Unit # 243E was submitted in error. Amoco never intended to perform a repair on that well. The Gallegos Canyon Unit # 243 was repaired in March of 1985 and a subsequent sundry was submitted on 4-12-85.

NOTE: This sundry is in response to File letter SF-078904 dated 11-20-86.

RECEIVED
DEC 29 1986
DIV.
1004-0135

18. I hereby certify that the foregoing is true and correct

SIGNED

B. Shaw

TITLE

Adm. Supervisor

DATE 12-16-86

ACCEPTED FOR RECORDS

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 12-23 1986

CONDITIONS OF APPROVAL, IF ANY:

FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side