UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

Lease Serial No. NMSF - 078106

Do not use thi	S form for proposals to	RIS UN W drill or to re	ELLO 🤏		NMSF - 078106	<u> </u>		
abandoned wel	s form for proposals to II. Use form 3160-3 (API	D) for such	proposals.	2002	6. If Indian, Allottee	or Tribe Name		
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well Oil Well	8. Well Name and No. GALLEGOS CANYON UNIT 297							
2. Name of Operator	9. API Well No.							
2. Name of Operator Contact: CHERRY HI BP AMERICA PRODUCTION COMPANY E-Mail: hlavac					30-045-23996			
3a. Address P.O. BOX 3092 HOUSTON, TX 77079	3b. Phone No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700			10. Field and Pool, or Exploratory PICTURED CLIFFS				
4. Location of Well (Footage, Sec., T.		11. County or Parish, and State						
Sec 15 T28N R12W NWNE 10			SAN JUAN COUNTY, NM					
12. CHECK APPR	COPRIATE BOX(ES) TO	INDICATE	NATURE O	F NOTICE, RI	EPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION		TYPE OF ACTION						
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off		
_	☐ Alter Casing	☐ Fra	cture Treat	☐ Reclama	ation	■ Well Integrity		
☐ Subsequent Report	Casing Repair	☐ Nev	v Construction	☐ Recomp	lete	Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plu	g and Abandon	Tempor	arily Abandon			
	☐ Convert to Injection	🗖 Plu	g Back	■ Water D	Pisposal			
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) On March 3, 2001 Amoco Production Company requested permission to continue the shut-in status for this well pending our well by well review to determine if an attempt may be made to restore it back to production either in the existing zone or uphole and avoid premature abandonment of possible reserves. Permission was granted 3/30/01. The well review is complete. We feel there could be possible reserves and wish to hold the well for possible future rehabilitation of the existing PC sand. Therefore we respectfully request to T&A the above mentioned well per the attached procedure.								
THIS APPROVAL EXPIRES FEB 1 5 2003								
14. I hereby certify that the foregoing is	true and correct. Electronic Submission # For BP AMERICA PR	10297 verified ODUCTION C	I by the BLM W OMPANY, sen	ell Information t to the Farming	System gton			
Name (Printed/Typed) CHERRY	Title AUTHORIZED REPRESENTATIVE							
O: (EL)								

Signature (Electronic Submission)

Date 02/06/2002

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

San Juan Basin Well Work Procedure

Well Name: Version: Date: Budget:	GCU 297 #1 2/6/2002 DRA				
Repair Type:	Temporary Abando	onment			
Objectives:					
1. TXA well	bore; hold for rehabilitation of	the existing	PC.		
Pertinent Info					
Location: County: State: Lease:	Sec 15 T28N R12W San Juan New Mexico			Horizon: API #: Engr: Phone:	Pictured Cliffs 30-045-23996 Allen Kutch (281)366-7955
	ps: (Estimated formation top				
Nacimento: Ojo Alamo:	193		nefee: nt Lookout:		
Kirtland Shale			ncos Shale:		
Fruitland:	1182	Ga!			
Pictured Cliffs	1455		neros:		
Lewis Shale:			ota:		
Chacra: Cliff House:		Moi	rison:		
Bradenhead 1	Test Information:				
Test Date:	Tubing:	Ca	sing:	BH:	
Time BH	CSG	INT	CSG		
5 min 10 min 15 min					
Comments:					

GCU 297 T&A.DOC


Temorary abandonment procedure

- 1. Contact Federal and State agencies prior to starting P&A work (NMOCD Charlie Perrin, 505-334-6178 X16, BLM 505-599-8907).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Check and record tubing casing and bradenhead pressures.
- 4. Blow down well and kill well, if necessary, with lease water.
- 5. ND wellhead. NU BOP's.
- 6. POOH with 2-3/8" tbg, visually inspecting.
- 7. Make bit x scraper run.
- 8. TIH with CIBP on tbg. Set CIBP at 1400' to TXA the Pictured Cliffs perfs.
- 9. Load well with inhibited lease water. Test casing to 550 psi for 30 minutes.
- 10. Land 2-3/8" tbg. ND BOP, NU WH.
- 11. RDMO SU.

GCU 297 T&A.DOC Page 2

GCU 297 - Proposed T&A Configuration San Juan County, NM Unit B Section 15 T28N - R12W Run 24

2-06-2002 ATK



PBCD: 1635'
CD: 1697'