

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

38. GEOLOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Ojo Alamo	507'	1437'				
Fruitland	1437'	1698'				
Pictured Cliffs	1698'	2645'				
Chacra	2645'	3000'				
Cliffhouse	3300'	3396'				
Menefee	3396'	4165'				
Point Lookout	4165'	5332'				
Gallup	5332'	6213'				
Dakota	6213'	TD				