5. LEASE

NOO-C-14

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Juda 8
SUNDRY NOTICES AND REPORTS ON WELLS to not use this form for proposals to drill or to deepen or plug back to a different servoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT HAME
servoir, Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil 🛣 gas 🗆 other	Duncan-Navaja 9. WELL NO.
2. NAME OF OPERATOR John F. Staver dba Saguaro Oil Company	10. FIELD OR WILDCAT NAME
3 ADDRESS OF OPERATOR	Wildcat 200 PLK AND STRIKEN OR
P. O. Box 51. Farminoton, N. M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	Sec. 14, J28N, RITW
below.)	12. COUNTY OR PARISH 13. STATE
AT SURFACE:	San Juan N. M.
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	14. API NO.
	Approved 3/8/74
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REPORT, OR OTHER DATA	5244 Gra 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
PEOUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	<u>J211 J14</u>
KEQUEUT TOK AUTHORITIES	
TEST WATER SHUT-OFF U	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING 🔲	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	
ABANDON* ₩ L	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	
Propose to plug and abandon April 7, 1974	
Jotal Depth 1547?, Jop Dakota 1446?, Jop Ga	Uup 578*
Set cement plug 1100' to 1547'	
Set cement plug 550° to 750°	
Set cement plug 0° to 10°	OIL CON 2977
Erect dry hole marker and clean location.	DIST. 3
. =	
Subsurface Safety Valve: Manu. and Type	70.
18. I hereby pertine that the foregoing is true and correct	

(This space for Federal or State office use)

_ TITLE ___

DATE