1			/
NO. OF COPIES RECEIVED			1
DISTRIBUTION		CONSERVATION COMMISSION	Form C-104
SANTA FE /	REQUES	T FOR ALLOWABLE	Supersedes Old C-104 and C-1 Effective 1-1-65
		AND	
LAND OFFICE	AUTHORIZATION TO TH	RANSPORT OIL AND NATURAL GA	AS
OIL OIL			
TRANSPORTER GAS /			
OPERATOR //			
PROBATION OFFICE			
Operator			
Tenneco Oil Compa	any		
P. O. Box 1714. I	Durango, Colorado 8130	1	
Reason(s) for filing (Check proper box)		Other (Please explain)	
New Well	Change in Transporter of:	Effective firs	st delivery
Recompletion	Oil Dry	Gas	
Change in Ownership	Casinghead Gas Cond	densate	
If change of ownership give name and address of previous owner			
DESCRIPTION OF WELL AND L	EASE		
Lease Name	Well No. Pool Name, Including		
Florance	61 Blanco Pic	tured Cliffs State, Federal	or Fee Fed \$F 07820
	O Feet From The North L	_ine and Feet From T	
DESIGNATION OF TRANSPORT	ER OF OIL AND NATURAL (	GAS Address (Give address to which approv	ed copy of this form is to be sent)
None Name of Authorized Transporter of Cast	inghead Gas or Dry Gas X	Address (Give address to which approv	ed copy of this form is to be sent)
_		P. O. Box 990, Farming	
El Paso Natural (		i . O. Dox 550, Parming	rton New Merico
	Unit Sec. Twp. Rge.	Is gas actually connected? Whe	
If well produces oil or liquids, give location of tanks.	Unit Sec. Twp. Rge. A 12 29 9	Is gas actually connected? Whe	
If well produces oil or liquids, give location of tanks.  If this production is commingled with	A 12 29 9	No	n
If well produces oil or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA	A 12 29 9  that from any other lease or pool on that from any other lease or pool on the form of the f	No ol, give commingling order number:	On Approval
If well produces oil or liquids, give location of tanks.  If this production is commingled with	A 12 29 9  In that from any other lease or poor	No ol, give commingling order number: New Well Workover Deepen	On Approval
If well produces off or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion	A 12 29 9  that from any other lease or pool on that from any other lease or pool on the form of the f	No ol, give commingling order number:	On Approval
If well produces oil or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion Date Spudded	A 12 29 9  In that from any other lease or poor $A = A = A = A = A = A = A = A = A = A =$	No ol, give commingling order number: New Well Workover Deepen	On Approval
If well produces of or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion  Date Spudded  2/4/66	A 12 29 9  In that from any other lease or poon $A = A = A = A = A$ Oil Well Gas Well X	No  No, give commingling order number:  New Well Workover Deepen  X  Total Depth	On Approval  Plug Back   Same Res'v. Diff. Res'
If well produces oil or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion Date Spudded  2/4/66  Elevations (DF, RKB, RT, GR, etc.)	A 12 29 9  In that from any other lease or pool of the from that from any other lease or pool of the from that from any other lease or pool of the from	No ol, give commingling order number: New Well Workover Deepen X Total Depth 3040 Top Oil/Gas Pay	On Approval Plug Back   Same Res'v. Diff. Res' P.B.T.D. 2790
If well produces of or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion  Date Spudded  2/4/66	A 12 29 9  In that from any other lease or pool in - (X)  Date Compl. Ready to Prod.  3/24/66	No ol, give commingling order number: New Well Workover Deepen X Total Depth 3040 Top Oil/Gas Pay	On Approval  Plug Back   Same Res'v.   Diff. Res'  P.B.T.D.  2790  Tubing Depth
If well produces oil or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion Date Spudded  2/4/66  Elevations (DF, RKB, RT, GR, etc.) 6279 Gr.	A 12 29 9  In that from any other lease or pool of the from that from any other lease or pool of the from that from any other lease or pool of the from	No ol, give commingling order number: New Well Workover Deepen X Total Depth 3040 Top Oil/Gas Pay	On Approval  Plug Back   Same Res'v.   Diff. Res'  P.B.T.D.  2790  Tubing Depth  None
If well produces oil or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion  Date Spudded  2/4/66  Elevations (DF, RKB, RT, GR, etc.) 6279 Gr.  Perforations	A 12 29 9  In that from any other lease or poor  In - (X) Gas Well  Name of Producing Formation  Blanco Pictured Cliff	No ol, give commingling order number: New Well Workover Deepen X Total Depth 3040 Top Oil/Gas Pay	Plug Back   Same Res'v. Diff. Res' P.B.T.D. 2790 Tubing Depth None Depth Casing Shoe
If well produces oil or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion  Date Spudded  2/4/66  Elevations (DF, RKB, RT, GR, etc.) 6279 Gr.  Perforations	A 12 29 9  In that from any other lease or poor  In - (X) Gas Well  Name of Producing Formation  Blanco Pictured Cliff	No ol, give commingling order number:  New Well Workover Deepen  X  Total Depth  3040  Top Oil/Gas Pay  2905	Plug Back   Same Res'v. Diff. Res' P.B.T.D. 2790 Tubing Depth None Depth Casing Shoe
If well produces of or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion Date Spudded  2/4/66  Elevations (DF, RKB, RT, GR, etc.) 6279 Gr.  Perforations  2905-2925	A 12 29 9  In that from any other lease or poor  In - (X)	No  No, give commingling order number:  New Well Workover Deepen  X  Total Depth  3040  Top Oil/Gas Pay  Es 2905	Plug Back   Same Res'v.   Diff. Res' P.B.T.D. 2790 Tubing Depth None Depth Casing Shoe 3038  SACKS CEMENT 100
If well produces oil or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion Date Spudded  2/4/66  Elevations (DF, RKB, RT, GR, etc.) 6279 Gr.  Perforations  2905-2925  HOLE SIZE  12-1/4"	A 12 29 9  In that from any other lease or poor  In - (X)	No ol, give commingling order number: New Well Workover Deepen  X Total Depth 3040 Top Oil/Gas Pay Es 2905  AND CEMENTING RECORD DEPTH SET	Plug Back   Same Res'v. Diff. Res' P.B.T.D. 2790 Tubing Depth None Depth Casing Shoe 3038
If well produces oil or liquids, give location of tanks.  If this production is commingled with COMPLETION DATA  Designate Type of Completion Date Spudded  2/4/66  Elevations (DF, RKB, RT, GR, etc.) 6279 Gr.  Perforations  2905-2925  HOLE SIZE	A 12 29 9  In that from any other lease or poor  In - (X)	No ol, give commingling order number: New Well Workover Deepen  X Total Depth 3040 Top Oil/Gas Pay Es 2905  AND CEMENTING RECORD DEPTH SET 180	Plug Back   Same Res'v. Diff. Res' P.B.T.D. 2790 Tubing Depth None Depth Casing Shoe 3038  SACKS CEMENT 100

Choke Size Tubing Pressure Casing Pressure Length of Test Gas - MCF Oil-Bbls. Water - Bbls. Actual Prod. During Test GAS WELL
Actual Prod. Test-MCF/D Bbls. Condensate/MMCF Gravity of Condensate Length of Test 3 hrs.
Tubing Pressure (Shut-in) 1733 Casing Pressure (Shut-in) Choke Size

924

Producing Method (Flow, pump, gas lift, etc.)

By Original Signed by Emery C.

## Back Pr. VI. CERTIFICATE OF COMPLIANCE

Testing Method (pitot, back pr.)

Date First New Oil Run To Tanks

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

Date of Test

7	n A Thomas	
	M. K. Wagner (Signature)	
	(Title)	

December 14, 1967

SUPERVISOR DIST This form is to be filed in compliance with RULE 1104.

OIL CONSERVATION COMMISSION DEC 15 1967

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

3/4"

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I, II, III, and VI for changes of owner, well name or number, or transporter or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.