Form 3160-5	UNITED STATES	SUBMIT IN TRIPLICATES	Form approved. Budget Buréau No. 1004-0135 Expires August 31, 1985
(November 1983) (Formerly 9-331)	DEPARTMENT OF THE IN	TERIOR (Other instructions on re-	5. LEASE DESIGNATION AND SERIAL NO.
(Poliment) 9-331)	BUREAU OF LAND MANAGE		1 1 2 2 1 1 2 4 6 2
			JACATILIA 463
SUNE	RY NOTICES AND REPOI	rts on Wells	
(Do not use this fo	orm for proposals to drill or to deepen of Use "APPLICATION FOR PERMIT" for	r plug back to a different reservoir.	Jicarilla Apache Tribe
1.	OR ATTECATION TO LEGISLATION		7. UNIT AGREEMENT NAME
OIL TO GAS T	7		
WELL - WELL -	OTES		8. PARM OR LEASE NAME
2. NAME OF OPERATOR	1		Jicarilla 463
Robert L. Ba	yress		9. WELL NO.
3. ADDRESS OF OPERATOR		DEATHIER	
	, Farmington, NM 87499	RECEIVED	1 10. FIELD AND POOL, OR WILDCAT
See also space 17 below	ort location clearly and in accordance w	ith any State requirements.	,
At surface		MAD 2 a 1007	Wildcat
1850' F	NL & 790 FWL	MAR 26 1987	11. SEC., T., E., M., OR BLK. AND SURVEY OR ARMA
		Bungali of Land Mahadania	a os =2011 pari
		BUREAU OF LAND MANAGEMENT	Sec. 25, T30N, R3W
14. PERMIT NO.		FARMING TON RESOURCE AREA	12, COUNTY OR PARISH 13. STATE
	7195 GL		Rio Arriba NM
16.	Charle A announce Box To India	cate Nature of Notice, Report, or O	lther Data
	Check Appropriate box to indic		
NO	TICE OF INTENTION TO:	DESECT	ENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOUT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other) Run product	ion casing cement X
(Other)		(Norz: Report results	of multiple completion on Well etion Report and Log form.)
See Attach	ed Daily Reports.		MAR 27 1987 L CON. DIV.
S. I hereby certify that the SIGNED	TITLE		ACCEPTED FOR RECORD
			MAR 26 1987

*See Instructions on Reverse Side

MAR 20 PARMINGTON RESOURCE AREA

ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING
P. O. BOX 168
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

DAILY REPORT

Jicarilla 463 #1
Sec. 25, T30N, R3W
1850' FNL & 790' FWL
Rio Arriba County, New Mexico

03/24/87 T.D. well at 8:15 a.m. 3/23/87 - Circulate for ½ hour - Short trip 20 stands - Circulate for 1½ hours - TOH for logs - Rigged up Welex - Ran IEL, FDC, CNL logs from 3975 to surface (note: bottom of hole was very tight, logged from 3975 not bottom) - T1H with drillpipe - circulate 3½ hours waiting on casing - LDDP and collars - ran 4½ csg as follows:

DESCRIPTION	LENGTH	DEPTH
KB to landing point	11.00	0-11
105 jts of $4\frac{1}{2}$ " 11.6#/ft new casing	3952.38	11-3963
1 DFFC	2.25	3963-3966
1 jt of $4\frac{1}{2}$ " 11.6#/ft new casing	42.18	3966-4008
1 guide shoe	1.00	4008-4009
	4008.81	

centralizers @ 3986, 3888, 3775, 3699, 3625, and 3550
Rigged up Dowell - cemented longstring casing with 200 sacks of class B cement with 2%D-79 (412ft) tailed by 175 sacks of 50/50 pozmix with 2% gel, 10% salt, and 1# flocele/sx (221 ft) - good circulation throughout job - bumped plug to 1850 psi - held ok - plug down at 6:00 a.m. 3/24/87 - set slips and rig down - Release Rig